

BUREAU OF RECLAMATION
Technical Service Center
Denver, Colorado

TRAVEL REPORT

Code: 86-68560

Date: June 28, 2006

To: Manager, Water Resources Research Laboratory

From: Tracy B. Vermeyen, 86-68560

Subject: Controlotron Flowmeter, Big Thompson Powerplant, near Loveland, Colorado.

1. Travel period: June 14, 2006.

2. Places or offices visited: Big Thompson Powerplant (BTPP) near Loveland, Colorado.

3. Purpose of trip: Review To service and troubleshoot the Controlotron flowmeter at Big Thompson Powerplant (Colorado-Big Thompson Project.)

4. Synopsis of trip: I traveled to Loveland, Colorado on the morning of Wednesday June 14, 2006. I arrived at the BTPP at 9:30 am where I met Phil Gregory, EC-6000. Phil and I discussed the problems with the flowmeter installation. The BTPP flowmeter consists of a single acoustic path mounted in reflect mode (transducers positioned on the same side of the pipe-figure 1). Size five transducers are used on this 67-inch outside diameter (OD) penstock. The wall thickness was 0.375 inches and the penstock has a 0.125 inch thick coal tar epoxy liner.

The purpose of this field visit was to inspect the flowmeter to determine why the flows are increasing to an unreasonably high value. At about 11:00 a.m. I turned off the power to the flowmeter and the flow was about 310 ft³/sec. This flow agreed closely to the BT Plant MW vs. Flowrate table displayed in the flowmeter enclosure.

I removed the transducers from their tracks and inspected the condition of the acoustic couplant. The downstream transducer was in good condition and the upstream transducer was in poor condition, i.e. the couplant was dried out. I cleaned the transducers and the pipe and re-applied a thin-layer of a long-lasting acoustic




Figure 1. Photograph (taken in 2000) of the Controlotron flowmeter installation. The old transducer location is also shown. The pipe has since been re-painted to cover the old transducer locations.

couplant. I left a tube of the couplant in the flowmeter

enclosure for future use. I re-installed the transducers in their original locations. I checked the transducer spacing which was 49.50 inches.

By 12:55 p.m. the installation was complete and the flowmeter was re-started. All the setup parameters were checked and no errors were found. The signal strength parameters were very good ($V_{lc}=75$ and $V_{aer}=8$) which is an indication of the quality of the installation. However, when I turned on the flowmeter it came up with a flow of $570 \text{ ft}^3/\text{sec}$ which was consistent with the erroneous flows the project operators had been observing.

At this point, I performed a new transducer installation (makeup) which included a "reversomatic" flow zero procedure since an actual zero offset procedure could not be performed. Again, when the flowmeter was enabled a flow of $570 \text{ ft}^3/\text{sec}$ was reported. After several makeup procedures the flowmeter reported a flow of $310 \text{ ft}^3/\text{sec}$. At this point, I began outputting the flowmeter data to a thermal printer to monitor the activity. After a few minutes, the flowmeter went through an In-process Makeup procedure, after which the flowmeter began reporting a flow of $570 \text{ ft}^3/\text{sec}$. The reason for the In-process Makeup is likely caused by turbulence or excessive aeration in the flow. The printout of flowmeter data showed an increase in V_{AER} from a value of 12 to 22 during the In-process Makeup incident. I checked with Controlotron technical support and they confirmed this diagnosis. Apparently, a disturbance in the flow causes the In-process Makeup routine to run and the flowmeter returns to operation in a "Mis-registered" state. This condition is indicated by an apparent Zero Offset equal to $\pm V_f \text{ max}$, which in this case was $+264 \text{ ft}^3/\text{sec}$. For example, the actual flow was $310 \text{ ft}^3/\text{sec}$ with an additional $264 \text{ ft}^3/\text{sec}$ which resulted in an apparent flow equal to $574 \text{ ft}^3/\text{sec}$. The simplest way to correct for this error is to subtract $264 \text{ ft}^3/\text{sec}$ from the high discharge reported by the flowmeter.

According to section 7.5 in the Controlotron 990 Portable Flowmeter manual, the reason the flowmeter switches from an accurate flow measurement to a "Mis-registered" state is because the poor flow conditions in the penstock can cause the flowmeter to go through an In-process Makeup which results in the flowmeter fixing on a secondary peak in the acoustic signal, rather than the primary peak. The next time the flowmeter goes through an In-process makeup it may or may not detect the primary peak. Eventually, it will re-acquire the primary peak and begin reporting the "true" discharge value.

The only changes that were made to the flowmeter installation were re-applying acoustic couplant to the transducer orientation from direct to reflect mode which required changing the transducer spacing. Note: I positioned the tracks so that the transducers could be mounted with a spacing of 49.56 inches which corresponds to placing pins in locations C-11 for a *reflect* track system. However, the tracks are for *direct* mount and they were positioned such that pin locations B-15 provided the correct transducer spacing. In order to get the transducer spacing close to the actual 49.5 inches I had to change the index from C-11 to D-10. For some reason I could not change the number index from 10 to 11. A possible fix to this is to reinstall the transducers and pick a different size transducer, say a size 4, then change it back to a size 5. This should reset the track index values to C-11. A print out of the site setup parameters is included in an appendix to this travel report.

After installation was complete, I collected data for a couple of minutes at a fifteen second interval, and the measured flowrate was very stable but was reading $560 \text{ ft}^3/\text{sec}$. While I was packing up my equipment, Phil

Travelers: Vermeyen

Date: June 28, 2006

kept cycling the power to the flowmeter until it re-registered to the correct flowrate. Then we left the plant, around 2:00 p.m.

I found this phone call record from 5/21/2003 which describes this same problem: Tim Walenter EC-electrician called with a flowmeter problem. The flow in the penstock was 330 ft³/sec which exceeds V_{fmax}=262 ft³/sec which leads to a re-register which causes the flow to be increased by V_{fmax}. I called Controlotron and talked to Jim Robertson and he said you can fix the problem in the Diagnostic menu using the Re-Register < Decrease Flow> , but this fix only lasts until the next time the unit In-process Makeup (power outage, disable channel, transducer cleaning, low signal, etc..). A permanent fix would be to reinstall the transducers in DIRECT mode which should double the V_{fmax} value. However, this will result in a reduction in flowmeter accuracy. To improve accuracy a second pair of transducers can be installed to correct for cross flow errors. Cross flow errors are corrected by using REFLECT mode for a single pair of transducers.

Miscellaneous Comments:

- According to Controlotron, upgrading the 990 flowmeter to their 1010 line of flowmeters will eliminate this problem, because they have improved their signal processing routines in their latest generation of flowmeter. The existing transducers would NOT have to be replaced, only the electronics.
- The ECAO flowmeter was configured to store a discharge measurement in the internal datalogger every 4 hours, with a circular memory setting, which means the oldest data will be overwritten by new data once the memory is full. There is enough memory to collect about 10 weeks of data. This data storage may be useful as a backup if the Sutron system were to go down for a period of time. Note: this stored data must be retrieved within a few weeks or the data may be overwritten by new data.
- The signal strength (Valc) was very strong for after the new couplant was applied. Valc provides an indication of the condition of the acoustic couplant. If the strength drops below 60, fresh acoustic couplant should be applied. Valc was about 60 when I re-applied couplant on 6/14/2006.
- A copy of this travel report should be kept in the flowmeters instrumentation cabinet for future reference.
- The physical transducer spacing should be should be changed to 48 inches from the current LTN value of 49.6 inches because the flowmeter is programmed for a LTN value of 48 inches. I can assist with this process if needed. An alternative to this would be to re-install the transducers and see if the C-11 index can be selected, then finish the installation process.

Travelers: Vermeyen

Date: June 28, 2006

Previous related reports:

- Water Resources Research Laboratory Travel Report, TR-98-18, *Controlotron Flowmeter Evaluation, Big Thompson Powerplant near Loveland Colorado*, dated August 12 and 19, 1998.
- Water Resources Research Laboratory Travel Report, TR-00-12, *Controlotron Flowmeter Evaluation, Big Thompson Powerplant near Loveland Colorado*, dated August 30, 2000.

5. Conclusions: The current Controlotron flowmeter installation at the Big Thompson Powerplant is periodically producing erroneous discharge readings because the flow conditions are causing the flowmeter to mis-register and produce a discharge that is offset by the value of V_{fmax} , 264 ft³/sec. This problem comes and goes depending on the flow conditions in the penstock. To correct this problem you can subtract 264 ft³/sec should produce the most accurate flow measurement possible for this instrument considering the site limitations mentioned above.

6. Action correspondence initiated or required: None.

cc: Area Manager, ECAO, Loveland, CO, Attention: EC-1000
Area Manager, ECAO, Loveland, CO, Attention: EC-6000 (Gregory, 2 copies)
Area Manager, ECAO, Loveland, CO, Attention: EC-1800 (Peterson, Conger)

bc: 86-68560 (Vermeyen)
86-68560 (*Travel Report file*)
86-68500

Travelers: Vermeyen

Page 5
Date: June 28, 2006

SIGNATURES AND SURNAMES FOR:

Travel to: Big Thompson Powerplant, near Loveland, Colorado

Date or Dates of Travel: June 14, 2006

Names and Codes of Travelers: Tracy B. Vermeyen, 86-68560

<u>Traveler</u>	<u>Date</u>
_____	_____
_____	_____
_____	_____

Noted and Dated by:

NOTED: _____
(Date)

Manager, Water Resources Research Laboratory

Travelers: Vermeyen

Page 6
Date: June 28, 2006

Appendix - Controlotron Flowmeter Settings

			RE INSTALLED XDCRS		
Print Date	06.14.06 12.55			Ia/Psen/V2	Vo
Site Load	Channel Disable	No		V3	Vo
	Site	BTPWR		V4	Vo
Pipe Data	Units	Inches		Relay Setup	Relay 1 Off
	Pipe OD	67.000			Relay 2 Off
	Pipe Material	Steel			Relay 3 Off
	Estimate Vps I/S	126000.020		Xcdr Mount	Relay 4 Off
	Wall Thickness	0.375			Xcdr Type 5
	Liner Material	Coal Tar			Xcdr Size Reflect ✓
	Liner Thickness	0.125		Site Adjustment	Spacing D10 ✓
Liquid Data	Liquid Type	Water 20C/68F			Empty Pipe Set 60.025
	Estimated Vs M/S	1447.000			Zero Flow Set 0.000
	Viscosity (CS)	1.000			Dampins Set 15.000
	Density (SG)	1.000			Slew Rate(F/S/S) 0.000
Flow Rate Units	Units (Vol/Mass)	Cubic Feet			Deadband Set 0.000
	Time Units	SEC			Memory or Fault Fault
	Display Range	Autorange		Flow Calibration	Memory Interval 60
	Display Scaling	CU FT/SEC			Calibration Type Intrinsic
Flow Total Setup	Units (Vol/Mass)	Cubic Feet			Calibrate Kc 0.000
	Resolution	000x0000		Diagnostics	Flow Rate 313.000
	Totalizer Mode	NETFLOW			Flow Total 88.558
	Batch/Sample Tot	0.000			Alarm Status
	Display Scaling	MCU FT			Vs 1449.372
Analog Span	Max Flow Rate	500.000			Valc 74.600
	Min Flow Rate	0.000			Vaer 8
	Max Vs (M/S)	1729.000			AUX1 0.000
	Min Vs (M/S)	1300.000			AUX2 0.000
Alarm Set	High Flow Alarm	960.231			AUX3 0.000
	Low Flow Alarm	-960.231			AUX4 0.000
	Interface Vs M/S	2099.998			fx 45
	Aeration Alarm	50			N 37
Stripchart Setup	Data Selected	Vo			n 13
	Scale Units	Percent of Span			x 16
	Time Interval	1 second			Vfmax 264.056
Datalogger Setup	Datalogger Mode	Off			Vs max (M/S) 1618.321
	Data Selected	Site Id			Vs min (M/S) 1201.300
		Date			TN 2537.654
		Time			TL 2466.678
		Average Flow			Ltn 47.960 ✓
		Flow			Sp. Gr. 1.000
		Total			Contour 0.988
		Vs			Reynolds # 7015476.072
		Valc			Delta T (uSECS) 4.922
		Aeration			Checksum 296C93F
		Alarms			Code 042194-0921
		Analog Inputs			Version 2.30
	Event Selected	None			Upper Flow Limit 950.332
	Los Interval Set	1 Min.			Lower Flow Limit -950.332
Analog Inputs	Aux 1 Enab	No			ANCAL 0.000
	Aux 1 High	4000.000			Empty Set 60.025
	Aux 1 Low	0.000			
	Aux 2 Enab	No			
	Aux 2 High	4000.000			
	Aux 2 Low	0.000			
	Aux 3 Enab	No			
	Aux 3 High	4000.000			
	Aux 3 Low	0.000			
	Aux 4 Enab	No			
	Aux 4 High	4000.000			
	Aux 4 Low	0.000			

Travelers: Vermeyen

Page 8
Date: June 28, 2006