

RECLAMATION
Managing Water in the West




Presented by Jessica Torrey
Materials Engineer
TSC, Materials & Corrosion Laboratory
jtorrey@usbr.gov
303-445-2376


Corrosion Webinar Series
PCCP at Reclamation

What is PCCP?


Prestressed Concrete Cylinder Pipe



Source: Pure Technologies, www.puretechltd.com



Lined-Cylinder Pipe



Embedded-Cylinder Pipe

Note: also non-cylinder pipe

What is PCCP?



Historical Perspective

- Reclamation specified PCCP from ~1960 to 1990
- Current Reclamation-owned active inventory:
~90 miles in 48 sections
- In the 1970's, Class II and IV wire were introduced, and one manufacturer in particular produced pipe with wire that has had high probability of failure
- After several failures, Reclamation stopped installing PCCP in 1990
- AWWA C301 and C304 are the manufacture and design standards

PCCP: Principle Causes of Failure

- **Corrosion of Wire leading to Breaks**
 - Defective prestressing wire
 - Incomplete encasement of wire with mortar/cement slurry
 - Insufficient mortar cover
 - Cracking of mortar
 - Carbonation of mortar




Ak-Chin Link Pipeline



Ak-Chin Link Pipeline



Santa Clara Conduit





CAP Causes and Extents Report

Reclamation PCCP Failures

- **1984- Central Utah Project (UT), Jordan Aqueduct Reach 3**
 - Failed one month after going into service
 - Defective wire had longitudinal cracks, was wound exceeding specified tensile stresses
 - 2.3 miles lined with steel liner at cost of ~\$5 million
- **1990- Central Arizona Project (AZ)**
 - 6.5 miles of 21' diameter PCCP siphons constructed from 1975-1980
 - Exposed 223 units, 40% were distressed and needed repair, 10% of those needed replacement
 - Estimated cost of implementing repairs at the time was \$117 million
- **2015- Central Valley Project (CA), Santa Clara Conduit**
- **2016- Navajo Indian Irrigation Project (NM), Kutz Siphon**

Santa Clara Conduit Failure

- Central Valley Project, California
- Saturday, August 1, 2015
- 10' long, 8' diameter PCCP section failed
- Failure mode: corrosion leading to broken wires
 - Corrosive soil
 - Microcracking and carbonation in mortar coating




Santa Clara Conduit Failure

- **Emergency Repair:**
 - Replaced with cement mortar lined and coated steel pipe



Kutz Siphon Failure

- Navajo Indian Irrigation Project, New Mexico (now BIA owned)
- Friday, May 13, 2016
- Two 40' long, 17.5' diameter PCCP sections failed
- Concrete and water projected 200'
- Lost 1,000 cfs into the San Juan River
- Put 75,000 acres of irrigated land out of service
- Failure mode: corrosion leading to broken wires



Kutz Siphon Failure

- **Emergency Repair:**
 - Replace with steel
 - Fill with CLSM, no corrosion protection
- **2017-2018 Repair:**
 - Line steel sections with epoxy
 - Install cathodic protection at repair



Lessons Learned

- **Prevention!**
 - Know your system- risk assessment
 - Regular electromagnetic (EM) inspections for wire breaks, 3-5 yrs
 - Timely action to address problem areas or institute more frequent monitoring
 - Install corrosion protection
 - Schedule future repairs/replacement for deteriorating sections
- **Prepare for future emergencies**
 - Have spare replacement sections and butt-straps on hand
 - Have design ready for future replacements
 - Have emergency action plan ready
- **Maintenance and planned repairs are cheaper than reacting to pipe breaks.**

Condition Assessment

- **Site Evaluation**

- Topographic and geologic evaluation: near-surface groundwater, high corrosivity soils, arroyos and washes
- Man-made features that could increase corrosion potential: electrical transmission lines, foreign line crossings, roadways
- Soil resistivity surveys or corrosivity laboratory analysis

- **Potential Surveys**

- Pipe-to-soil/close interval survey or cell-to-cell survey
- Conducted above ground to identify areas of anomalous potential gradients indicating corrosion is occurring

Condition Assessment

- **Visual Inspection (Pipe Interior)**
 - Cracks in core
 - Leaks at joints
- **Acoustic Inspection**
 - Manual sounding- delamination of concrete or un-grouted areas/hollows
 - Impact Echo Testing- delamination, hollows, cracks
 - Free-floating acoustic sensor- leak detection
- **Electromagnetic Inspection**
 - Number and location of prestressing wire breaks
 - Can be conducted for in-service or dewatered pipe
- **Acoustic Fiber Optic Monitoring**
 - Continuous monitoring for wire breaks
 - Cables installed inside pipe
 - Requires monthly/annual monitoring contract




Repair Methods

- **Interior Crack and Joint Repair**
 - Reclamation's "Guide to Concrete Repair, 2nd ed."
 - Surface preparation, repair product application, curing
- **Installation of Cathodic Protection**
 - Requires electrical continuity of protected sections
 - Should not be polarized more negative than $-1000 \text{ mV}_{\text{CSE}}$ to avoid hydrogen embrittlement
- **Wire Splicing and Tendon Wrapping**
 - Exterior repair requiring pipe excavation
 - Use anchor blocks and tensioning devices to install replacement wire or tendons
- **Structural Liner**
 - Internal repair to provide structural support for distressed sections
 - Carbon Fiber Reinforced Polymer (CFRP)
 - Spray-in-Place Pipe (SIPP)



Current PCCP Activities in TSC

- **Science & Technology Program research projects (Research Office)**
 - ST-2019-7108-01/TM 8540-2019-31
PCCP: Condition Assessment, Repair, Replacement Strategies
 - FY19-22: PCCP Educational Demonstration
- **Inventory and GIS-Viewer for PCCP (Joint RO and PO)**
- **PCCP electromagnetic inspections (Policy Office)**
 - Fund and award contract for EM inspection of prioritized Reclamation-owned PCCP installations
 - Coordinate and facilitate inspections
 - Compile all inspection data into PCCP database
 - TM OOP-PCCP-8140-RA-2019-1
Risk Analysis Process for Prestressed Concrete Cylinder Pipe



PCCP Inventory

- **Tabular inventory of Reclamation-owned PCCP**
- **Collected:**
 - Basic pipe specs: age, diameter, length, operating pressure
 - Design data, as-built drawings, specs
 - Inspection reports
 - Monitoring or cathodic protection details
 - Details of repairs/replacements
- **Data linked to GIS-Viewer**

Region	State	Project	# PCCP Sections	Length (miles)	Construction Year(s)
LC	AZ	Ak-Chin Indian Water Rights Settlement	3	15.7	1981
LC	AZ	Central Arizona	21	23.5	1980-1992
LC	AZ	Salt River	3	0.5	1992
MP	CA	Central Valley	9	27.3	1986-1987
MP	CA	Ventura River	3	2.5	1958
PN	WA	Columbia Basin	1	0.4	1976
UC	CO	Dolores	7	18.5	1982-1992
UC	UT	Central Utah	1	0.2	1987
TOTAL:			48	89	

PCCP Web-based Geospatial Viewer

- **Confirm all PCCP on map (start and end locations only)**
 - Tool: visualize PCCP locations and identify those in proximity to high risk areas (high population, gas/power lines, etc.)
- **Populate Master Table**
 - Tool: manually query database to find high-risk sections (i.e., search for any pipe with max press > 650 and # breaks > 15)
- **Tie Master Table to Graphic Data Table**
 - Tool: query database and then locate exact pipe on map
 - Tool: snapshot summary box for each pipe
- **Collect and Tie Relevant Documents to Database (ongoing)**
 - Tool: access documents associated with a given PCCP section directly from map
- **Stationing and Association with # of wire breaks (future work)**
 - Tool: visualize wire breaks along pipe layout on map; see if breaks are dispersed or clustered

[PCCP Viewer Demo](#)

Resources

- **TSC – Materials and Corrosion Laboratory (S&T Research Projects)**
 - POCs Jessica Torrey and Matt Jermyn
 - [Project ID 7108: Critical Review of PCCP at Reclamation](#)
 - [Project ID 19275: PCCP Inspection Truthing and Educational Demonstration](#)
- **TSC – Water Conveyance Group (EM Inspection Coordination)**
 - POCs Kylie Pelzer and Chris Duke
- **Policy Office – Asset Management Division (Inspection Contract and Viewer)**
 - POC Nick Casamatta
- [Corrosion Webinar Series](#)

Questions/Comments/Discussion

Materials and Corrosion Laboratory Staff - 8540

Cathodic Protection



Chrissy Henderson
chenderson@usbr.gov
303-445-2348



Matt Jermyn
mjermyn@usbr.gov
303-445-2317




Daryl Little, Ph.D.
dlittle@usbr.gov
303-445-2384



David Tordonato, Ph.D., P.E.
dtordonato@usbr.gov
303-445-2394



Jessica Torrey, Ph.D.
jtorrey@usbr.gov
303-445-2376



Grace Weber
GWeber@usbr.gov
303-445-2327

Hazardous Materials



Lise Pederson, PE
lpederson@usbr.gov
303-445-3095



Kevin Kelly, Ph.D
KKelly@usbr.gov
303-445-7944

Protective Coatings



Brian Baumgarten
bbaumgarten@usbr.gov
303-445-2399



Carter Gulsvig
cgulsvig@usbr.gov
303-445-2329



Bobbi Jo Merten, Ph.D.
bmerten@usbr.gov
303-445-2380



Rick Pepin, PCS
rpepin@usbr.gov
303-445-2391



Stephanie Prochaska
sprochaska@usbr.gov
303-445-2323



Allen Skaja, Ph.D., PCS
askaja@usbr.gov
303-445-2396