

**The Degraded Reach:
Rate and Pattern of Bed and
Bank Adjustment in the First
25 km Downstream from Glen
Canyon Dam**

**Paul Grams, David Topping, Jack Schmidt,
and Sara Goeking**

Why Study Glen Canyon?

- Has bed degradation continued since 1975?
- What has been the spatial distribution of bed degradation within Glen Canyon?
- How have channel-side alluvial deposits changed since the pre-dam period?


Components of Study

- Changes in bed elevation
 - Reclamation monitoring cross-sections
 - USGS gage station records of bed elevation
- Channel-side deposits
 - Mapping from historical aerial photographs
 - Historical oblique photographs
 - Comparison with cross-section data

The Reclamation monitoring “Ranges”



Lees Ferry Gaging Station



Glen Canyon - 1956



PP-1591

Glen Canyon 1889 - 1992



1889



1992

Glen Canyon 1956 - 2000



July 1956




September 2000

Glen Canyon 1954 - 1999


1956




1998






Glen Canyon Location Map



Lees Ferry Upper Cableway Minimum Bed Elevation





“Channel Cleaning” Flows





Cross section showing bed degradation, 1956-2000

Range 16, 4.3 km downstream from Glen Canyon Dam





Cross section showing bed degradation, 1956-2000

Range 11a, 10.3 km downstream from Glen Canyon Dam





looking downstream


Minimum bed elevation from 1956 to 2000 for cross-sections located in riffles and pools




Adjustment of Stage-Discharge Relations: Greatest at upstream end of Reach




Drop in Stage-Discharge Relation Decreases with Distance Downstream




Eroded bank and “Perched” terrace 10.3 km downstream from Glen Canyon Dam



Longitudinal Profile of Bed Degradation: 1956 - 2000



Accumulated sediment evacuation from Glen Canyon



8.3 million m³ sediment evacuation predicted in 1957


9.9 million m³ measured in 1975

10.7 million m³ measured in 2000 – exceeds predicted by ~ 30%



Changes in Channel-Side Deposits

- Measurements at Lees Ferry Lower Cableway provide long pre- and post-dam time series for one location
- Mapping from aerial photographs provides comprehensive coverage from the dam to Lees Ferry

Progressive decrease in channel width at Lower Cableway




Bed Scour and bank deposition at Lower Cableway



Mapping from Air Photos


The Degraded Reach: Rate and Pattern of Bed and Bank Adjustment in the First 25 km Downstream from Glen Canyon Dam

Plate 2 – Erosion-Deposition overlay, September 1952 to October 1984 Reaches 1 and 2 (0 to 10.3 km downstream from Glen Canyon Dam)




The Degraded Reach: Rate and Pattern of Bed and Bank Adjustment in the First 25 km Downstream from Glen Canyon Dam


Plate 3 – Erosion-Deposition overlay, September 1952 to October 1984 Reaches 3 to 5 (10.3 to 25.2 km downstream from Glen Canyon Dam)




Erosion of pre-dam terrace 1952 to 1984




Erosion and “perching” of channel-side deposits: 1952 to 1984




Sketch of Pre- and Post-Dam Channel Cross-Section



Changes in the area of alluvial deposits: 1952 to 1996



Downstream distribution of changes in alluvial deposits: 1956 to 1984



Conclusions I

- Sediment evacuation from Glen Canyon has continued since 1975, but at a much reduced rate
 - Has not significantly decreased mean bed elevations
 - Most degradation since 1975 occurred in pools
 - Magnitude of degradation in riffles decreases in downstream direction and extends downstream to 2 mi above Lees Ferry
 - Magnitude of degradation in pools does not correlate with distance downstream and extends below Lees Ferry
- The stage discharge relations have dropped by up to 1 m at the upstream end of the reach and have not changed at the downstream end of the reach

Conclusions II

- Massive terrace erosion at localized sites during the channel cleaning flows, not widespread throughout reach and current rates of erosion are very low
- Channel-side sand deposits and gravel deposits “perched” above active channel and stabilized by vegetation

Prognosis

- Continued evacuation of sediment from pools, primarily during floods
- No further degradation of channel controls (riffles), even during floods
- Possible aggradation of riffles over time and in the absence of scouring floods
- Subtle changes to channel-side deposits
 - Sporadic and localized terrace erosion
 - Small-scale erosion and deposition at sand bars