




APPENDIX A

Asaayi Dam Modifications



PROFILE ALONG & OUTLET WORKS WITH PRESSURIZED DOUBLE LINER



NOTES
Reinforcement required but not shown.

ALWAYS THINK SAFETY
 ALWAYS WEAR YOUR SAFETY GEAR
 BE AWARE OF YOUR SURROUNDINGS
 BE AWARE OF THE WEATHER
 BE AWARE OF THE RISK OF FALLING
 BE AWARE OF THE RISK OF COLLISION
 BE AWARE OF THE RISK OF ELECTRICAL SHOCK
 BE AWARE OF THE RISK OF FIRE
 BE AWARE OF THE RISK OF DROWNING
 BE AWARE OF THE RISK OF OTHER HAZARDOUS CONDITIONS

ASAAYI DAM
 DUAL-CONTAINMENT HDPE LINER

FIGURE 9A - VE, PROPOSAL 5

CONTRACT NO. 18-05
 PROJECT NO. 18-05
 COUNTY OF SAN JUAN, NEW MEXICO