



FIGURE 3.12-18A VIEW FROM VIEWPOINT #6, PHOTO 1 GATES-OUT CONDITION



FIGURE 3.12-18B VIEW FROM VIEWPOINT #6, PHOTO 1 GATES-IN CONDITION

EAST SAND SLOUGH VIEWPOINT #6
FISH PASSAGE IMPROVEMENT PROJECT
RED BLUFF DIVERSION DAM EIS/EIR



FIGURE 3.12-19A VIEW FROM VIEWPOINT #6, PHOTO 2 GATES-OUT CONDITION



FIGURE 3.12-19B VIEW FROM VIEWPOINT #6, PHOTO 2 GATES-IN CONDITION

EAST SAND SLOUGH VIEWPOINT #6
FISH PASSAGE IMPROVEMENT PROJECT
RED BLUFF DIVERSION DAM EIS/EIR



FIGURE 3.12-20A VIEW FROM VIEWPOINT #7 **GATES-OUT CONDITION**



FIGURE 3.12-20B VIEW FROM VIEWPOINT #7 GATES-IN CONDITION

EAST SAND SLOUGH VIEWPOINT #7
FISH PASSAGE IMPROVEMENT PROJECT
RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL -






FIGURE 3.12-22A VIEW FROM VIEWPOINT #8 **GATES-OUT CONDITION**



FIGURE 3.12-22B VIEW FROM VIEWPOINT #8 GATES-IN CONDITION

MIDDLE RIVER VIEWPOINT #8
FISH PASSAGE IMPROVEMENT PROJECT
RED BLUFF DIVERSION DAM EIS/EIR



FIGURE 3.12-23A VIEW FROM VIEWPOINT #9, PHOTO 1 GATES-OUT CONDITION



FIGURE 3.12-23B VIEW FROM VIEWPOINT #9, PHOTO 1 GATES-IN CONDITION

MIDDLE RIVER VIEWPOINT #9
FISH PASSAGE IMPROVEMENT PROJECT
RED BLUFF DIVERSION DAM EIS/EIR



FIGURE 3.12-24A VIEW FROM VIEWPOINT #9, PHOTO 2 GATES-OUT CONDITION



FIGURE 3.12-24B VIEW FROM VIEWPOINT #9, PHOTO 2 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR



FIGURE 3.12-25A VIEW FROM VIEWPOINT #10, PHOTO 1 GATES-OUT CONDITION



FIGURE 3.12-25B VIEW FROM VIEWPOINT #10, PHOTO 1 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL ·



FIGURE 3.12-26A VIEW FROM VIEWPOINT #10, PHOTO 2 GATES-OUT CONDITION



FIGURE 3.12-26B VIEW FROM VIEWPOINT #10, PHOTO 2 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL ·



FIGURE 3.12-27A VIEW FROM VIEWPOINT #10, PHOTO 3 GATES-OUT CONDITION



FIGURE 3.12-27B VIEW FROM VIEWPOINT #10, PHOTO 3 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL



FIGURE 3.12-28A VIEW FROM VIEWPOINT #10, PHOTO 4 GATES-OUT CONDITION



FIGURE 3.12-28B VIEW FROM VIEWPOINT #10, PHOTO 4 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL



FIGURE 3.12-29A VIEW FROM VIEWPOINT #11 GATES-OUT CONDITION



FIGURE 3.12-29B VIEW FROM VIEWPOINT #11 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR

- CH2MHILL ·



FIGURE 3.12-30A VIEW FROM VIEWPOINT #12 GATES-OUT CONDITION



FIGURE 3.12-30B VIEW FROM VIEWPOINT #12 GATES-IN CONDITION

FISH PASSAGE IMPROVEMENT PROJECT RED BLUFF DIVERSION DAM EIS/EIR