

URS	17324004 San Luis Drainage Feature Re-evaluation	MIKE 21 Chipps Discharge (July to November 1997) Mean Total Selenium Concentration (TOP) Difference from Existing Conditions (BOTTOM)	FIGURE 6.1-4