Figure IV-23. Whittemore Gauge



Typical Installation Showing Measurement Points