Medicine Creek Todge

921-Modicine Creek Todge

921-Modicine Creek Todge

Medicine Creek Todge

TAB

TAB

Side 1.386



\$ 7 N

STATE OF NEBRASKA



Mike Johanns Governor DEPARTMENT OF ENVIRONMENTAL QUALITY
Michael J. Linder

Director
Suite 400, The Atrium
1200 'N' Street
P.O. Box 98922
Lincoln, Nebraska 68509-8922
Phone (402) 471-2186
FAX (402) 471-2909

AUG 1 9 2003

Mr. & Mrs. Roger Houser Route 2, Box 93 Cambridge NE 69022

RE:

Facility Name: Medicine Creek Lodge

Fire Marshal ID#: 8025 UG#: 091593-GW-1456 City: Cambridge, Nebraska

Dear Mr. & Mrs. Houser:

The Department has reviewed the Closure Assessment Report dated August 23, 1993, submitted for the above-referenced facility. You have advised this Agency that you are financially unable to proceed with the necessary remedial action at the above-referenced facility. The information available to the Department confirms your claim.

Therefore, we are placing your facility on the Leaking Underground Storage Tank (LUST) Trust Fund Priority List. Your facility will be addressed by the Department according to priority and as federal or state funds become available. In accordance with the Petroleum Products and Hazardous Substances Storage and Handling Act (§ 81-15, 124.02), the Department has the authority to access the property for purposes of performing remedial action.

Although the Department considers you financially unable to meet additional remedial action costs, this determination does not relieve your responsibility to pay for any remedial action costs previously incurred.

If your financial situation improves in the future, the Department or the U.S. EPA may seek cost recovery for funds spent on remedial actions taken at your facility. If information you provided is found to be substantively inaccurate, cost recovery may be sought, and the matter may be referred to the Attorney General for appropriate action. If you have any questions, please feel free to contact me at (402) 471-4230.

Sincerely,

Tammie Holley

Administrative Assistant Petroleum Remediation Section

Water Quality Division



MEMORANDUM

То:	File: UG#091593-GW-1456; Medicine Creek Lodge
Through:	David Chambers
From:	Tammie Holley
Date:	August 15, 2003
Re:	Request for site to be placed on the LUST Trust Fund Priority List.
To be completed	by Unit Supervisor:
Approved Date:	8-15-03 Rejected Date:
Initials:	
Comments:	
NOTE:	If this request is approved, this memo must be routed to the Procurement Coordinator before returning to the project manager or protocol group.
Procurement Cook	rdinator's Initials: Date: 8-15-03
To be completed	by project manager or protocol group:
Site Name: Medi Location: SW sid	icine Creek Lodge e of Strunk Lake
City: Cambridge	, Nebraska
Notifications mad	le (HHS, Local Water Commissioner, etc.):

History of the site, including actions taken to establish identity of RP, work performed to date at site, reason for placing it on PL, etc.:

The RP's, Roger and Patricia Houser, are financially unable to proceed with remedial actions.



To:

File

From:

David Chambers 782

Date:

August 12, 2003

RE:


Roger and Patricia Houser

Medicine Creek Lodge, Cambridge

UG# 091593-GW-1456

Based on her review of information provided, Kris Young (DEQ Fiscal Section) has recommended to me that the RP for this site(s) is financially unable to proceed with remedial actions. After reviewing the information, I agree and hereby determine the RP to be insolvent. This site(s) should be placed on the Priority List for orphan sites. If this site is eligible for the use of federal LUST Trust Fund monies, and if federal LUST Trust Fund monies are used for any remedial actions at the site, cost recovery actions will not be pursued unless the RP's financial condition sufficiently improves.

11/24 20875



7-7-03

Roger + I received the Tier 1 Site Investigation Work Plan and can not afford the cost of Propsal #03-038.

We beieve we did all we were required to do in 1993 when we pulled the underground tank . Burton Well Drilling excavated soit, replaced with clear dirt, areated the containated ect.

The owner who placed the tank has passed, the owner we bought it from has left the area.

We will be happy to give you any other information we can but feel Mr. Wilkinson did a good job in assessing our situation.

> In good faith. Patricia A. + Roger D. House Route 2 Bex 93

Cambridge NI. 69022 308 -697 -3774





June 9, 2003

Roger and Patricia Houser Medicine Creek Lodge RR 2 Box 88 Cambridge, NE 69022

RE: Tier I Site Investigation Work Plan, Medicine Creek Lodge, Cambridge,

NE

Proposal #03-038

Dear Mr. and Mrs. Houser:

Saberprobe LLC (SL) is pleased to submit this Tier I Site Investigation Work Plan for the above-referenced site, in Cambridge, NE. SL understands that this work plan is in support of a Nebraska Department of Environmental Quality (NDEQ) Risk Based Corrective Action (RBCA) investigation.

SL has proposed the following scope in accordance with the NDEQ soil and groundwater sampling requirements.

The scope of this proposal is based on NDEQ Tier I requirements and a site reconnaissance performed at the Medicine Creek Lodge in April, 2003 by SL.

Scope of Work

Prior to sampling and drilling activities, SL will coordinate a utility locate with Nebraska One-Call utility locating services. SL will coordinate with you on the time and date to meet onsite.

SL will probe 4 locations at this site with a Geoprobe[®] Model 6610dt probe unit. The proposed locations (see attached map) meet the NDEQ requirements for investigating a potential source area. Soil samples will be collected continuously using the macro core soil sampling system to approximately 35' below ground surface (or groundwater level). Soil samples will be logged and prepared for field analysis with a photoionization detector as per the NDEQ guidance for soil screening. Up to three soil samples from each location may be preserved and submitted for laboratory analysis for NDEQ RBCA analytical requirements.

After soil samples have been collected, SL will use 4 ¼" hollow stem augers to drill and install four – 2" PVC monitoring wells as per NDEQ monitoring well requirements. After installation, the wells will be purged and developed, then sampled for NDEQ RBCA groundwater analytical requirements. Groundwater samples will be collected with polyethylene disposable bailers. SL will also survey each well, and record static water levels using an electronic water level indicator. SL estimates depths of 35' to 40' feet for monitoring well installation.

The disposal of any investigation derived waste (IDW) or decontamination (decon) water generated will be coordinated and performed by SL unless otherwise arranged. All sampling tools will be decontaminated in between probe locations to avoid cross contamination.

After laboratory analysis has been completed, SL will prepare and submit two copies of a Nebraska Tier I Site Investigation report to you. The report will include all required information outlined in the NDEQ's "RBCA at Petroleum Release Sites" document. It is estimated that the time required to complete the field investigation and report will be three to four weeks.

Fees

SL's fees for these activities are described below. Please note that if the site conditions indicate that additional work is required based on discovery of on-site free-phase product, permission will be sought from you prior to proceeding with further activities. A cost estimate of costs for additional monitoring wells is included as per NDEQ requirements in the case free-phase product is discovered.

DESCRIPTION	FEES
Mobilization	\$1702.50
-14 hours roundtrip @ \$40.00/hour (\$560.00)	
-850 miles @ \$1.25/mile (\$1062.50)	
-mob/demobilization, 2 hours @ \$40.00/hour (\$80.00)	
Geoprobe® Model 6610dt, 2-man crew (16 hours @ \$125/hour)	\$2000.00
Macro Core Liners (32 @ \$3.00/ea.)\$96.00	\$96.00
Well Materials	\$769.00
-8 – 10' section, sch. 40, 2" PVC riser @ \$17.00/ea. (\$136.00)	
-4 – 10' section, sch. 40, 2" PVC Screen @ \$20.00/ea (\$80.00)	
-4 threaded 1" PVC end caps @ \$5.00/ea. (\$20.00)	
-4 locking J-Plugs @ \$17.00/ea (\$68.00)	
-24 – 50# bags filter pack @ \$6.50/ea. (\$156.00)	
-14 – 50# bags granular bentonite @ \$7.50/ea. (\$105.00)	
- 4 flush mount covers\$45.00/ea. (\$180.00)	
- 4 – 50# bags rapid set U-Mix @ \$6.00/ea. (\$24.00)	
E-Line (2 days @ \$20.00/day)	\$40.00

	Laboratory Analysis -4 Groundwater @ \$96.50/ea. (\$386.00) -up to 10 soil @ \$96.50/ea. (\$965.00)	\$1351.00
Г	Decon Labor and Equipment (2 days @ \$85.00/day)	\$170.00
	Photoionization Detector (2 days @ \$200.00/day)	\$200.00
	Per Diem (2 man crew, 2 days @ \$100.00/day)	\$200.00
	Report Preparation, 20 hours @ \$61.00/hour)	\$1220.00
	Senior Review, 1 hour @ \$71.00/hour	\$71.00
T	otal Fee Will Not Exceed	\$7819.50
C	ost for each additional monitoring well	\$750.00

Please call me with any questions or comments. If this work plan proposal is acceptable please sign below and return a copy to SL.


We appreciate the opportunity to work with you. If you have any questions, please feel free to call my office at (402)502-6848.


Respectfully submitted,
Saberprobe LLC

John D. Wilkinson

President

ACCEPTED BY:_____DATE:___







Nebraska Department of Environmental Quality LUST/RA Section

Tier 1 Site Investigation Work Plan Form

roview	process	rtment has developed this document to simplify the petrolcum release site investigation work plan. This form must be signed and dated by representatives of both the responsible party and the selected to perform the work. The form must include the following attachments:
	A site	e diagram (to scale) showing:
	1.	Major surface structures (buildings, streets, etc.) on or adjacent to the site;
	2.	Potential source area(s);
	3.	The location of any on-site water supply wells and surface water bodies within 500 feet of the site;
	4.	The location of any buildings, basements, and utilities within 200 feet of the site;
	5.	Selected sampling and/or drilling locations; and
	6.	An arrow indicating the anticipated direction of ground water flow
	Reported to the control of the contr	tailed cost estimate for conducting the Tier 1 investigation and submitting a Site Investigation of the Department. The report must provide all information outlined in the Department's commental guidance document, Risk-Based Corrective Action (RBCA) at Petroleum Release: Tier 1/Tier 2 Assessments and Reports (February 2002).
	free-p many	parate cost estimate for the installation of additional permanent monitoring wells in the event that phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well
	free-p many basis	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge
	free-p many basis	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin.
-	free-p many basis	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge
-	free-p many basis	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge NDEQ release number: UG # 091593-GW-1456 Responsible party signature date
-	fice-i many basis. You	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge NDEQ release number: UG # 091593-GW-1456 Responsible party signature Sober probe LLC Consultant company name
-	fice-i many basis. You	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge NDEQ release number: UG # 091593-GW-1456 Responsible party signature Sober probe LLC Consultant company name
-	free-t many basis. You i	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge NDEQ release number: UG # 091593-GW-1456 Responsible party signature date
-	free-t many basis. You i	phase product is encountered during the site investigation. Since it is not possible to foresee how wells might be required to delineate the free product plume, this estimate must be on a per-well must receive written notification from the Department before the site investigation may begin. Site name: Medicine Creek Lodge, Cambridge NDEQ release number: UG # 091593-GW-1456 Responsible party signature date Saber probe LLC Consultant company name 27 North 21st Street An Malaire

The completed form and attachments should be mailed to John K. Fogerty, NDEQ LUST/RA Section, Box 98922, Lincoln, NE 68509-8922 on or before May 9, 2003. Forms may also be faxed to (402) 471-2909, with the signed original following by mail.

	Laboratory Analysis -4 Groundwater @ \$96.50/ea. (\$386.00) -up to 10 soil @ \$96.50/ea. (\$965.00)	\$1351.00
	Decon Labor and Equipment (2 days @ \$85.00/day)	\$170.00
	Photoionization Detector (2 days @ \$200.00/day)	\$200.00
	Per Diem (2 man crew, 2 days @ \$100.00/day)	\$200.00
	Report Preparation, 20 hours @ \$61.00/hour)	\$1220.00
	Senior Review, 1 hour @ \$71.00/hour	\$71.00
T	otal Fee Will Not Exceed	\$7819.50
C	ost for each additional monitoring well	\$750.00

Please call me with any questions or comments. If this work plan proposal is acceptable please sign below and return a copy to SL.

We appreciate the opportunity to work with you. If you have any questions, please feel free to call my office at (402)502-6848.

Plase Sign + Return

Respectfully submitted, Saberprobe LLC

John D. Wilkinson President

ACCEPTED BY: DATE:



STATE OF NEBRASKA



Mike Johanns Governor

> Patricia A. Houser Medicine Creek Lodge RR 2 Box 88

DEPARTMENT OF ENVIRONMENTAL QUALITY Michael J. Linder

Suite 400, The Atrium 1200 'N' Street

P.O. Box 98922 Liricoln, Nebraska 68509-8922 Phone (402) 471-2186 FAX (402) 471-2909

web site: www.deq.state.ne.us

FILE COPY

8 2003

Cambridge NE 69022

RE: Notification to Prepare the Tier 1 Site Investigation Work Plan Form

Medicine Creek Lodge, Cambridge

UG # 091593-GW-1456

Dear Ms. Houser:

The Department has reviewed the *Tier 1 Pre-Investigation Assessment Work Plan Form* (dated April 4, 2003) submitted for the above referenced site. This work effort is approved and the cost estimate appears to be reasonable for the described scope of work. This letter does not serve to preapprove the cost of the work effort. In addition, this does not guarantee that the total estimated cost will be found eligible for reimbursement under Title 200. The actual reimbursement will be determined only after documentation of the work effort has been received and a Title 200 application has been submitted and evaluated. A Title 200 application may be submitted following completion of the Tier 1 site investigation report.

APR

The approval given should not be considered a certification of the consultant or guarantee of the consultant's work product or of any claims made as to the results to be accomplished. The consultant is not relieved from fully complying with any other state or federal laws or regulations, nor does approval relieve the owner/operator from criminal or civil penalties for violations which may have occurred. The Department's review is limited to assuring that the minimum information requirements have been included.

The pre-investigation assessment must be completed according to the information outlined in Risk-Based Correction Action (RCBA) at Petroleum Release Sites: Tier1/Tier2 Assessments & Reports (February 2002) environmental guidance document, and a Tier 1 Site Investigation Work Plan Form, including all attachments, must be submitted to the Department on or before May 9, 2003. Failure to submit the receivable by this date may result in a reimbursement reduction.

Thank you for your cooperation in this matter. If you have any questions or comments, please contact me at (402) 471-4230. Please include the facility name and file number as referenced at the top of this letter in any correspondence to this office from yourself or your consultant.

Sincerely.

John K. Fogerty, Geologist

LUST/RA Section Water Quality Division

Enclosure

Tier 1 Site Investigation Work Plan Form

c: John Wilkinson - Saberprobe





Nebraska Department of Environmental Quality LUST/RA Section

2003

Tier 1 Pre-Investigation Assessment Work Plan Horm

DEPARTMENT OF ENVIRONMENTAL QUALITY

The Department has developed this document to simplify the petroleum release site investigation work plan review process. The completed form must be signed and dated by representatives of both the responsible party and the consulting firm selected to perform the work.

The LUST program requires that a pre-investigation assessment, including a site visit, be conducted prior to conducting a Tier 1 site investigation in accordance with the Department's environmental guidance document, Risk-Based Corrective Action (RBCA) at Petroleum Release Sites: Tierl/Tier2 Assessments and Reports (February 2002), Section 3. The purposes of this assessment include, but are not limited to:

- 1. Conduct an on-site reconnaissance to determine potential source areas and potential complications for sampling the source areas;
- 2. Locate any water supply wells and surface water bodies within 500 feet of the site;
- 3. Locate utilities, buildings, and basements within 200 feet of the site as an aid in determining potential site complications;
- 4. Determine the appropriate sampling and/or drilling locations to obtain the required Tier I information:
- 5. Prepare a site diagram (to scale) showing the potential source area(s), selected sampling and/or drilling locations, and on-site water supply wells, basements, and utilities;
- 6. Prepare a proposed cost estimate for the planned site investigation; and
- 7. Prepare a separate, per-well cost estimate for additional monitoring wells to be installed if free product is encountered.

Estimated total cost for conducting the pre-investigation assessment:

\$_O.00

You must receive written notification from the Department before the pre-investigation assessment may begin.

Site name: Medicine Creek Cambridge, Nebraska NDEO release number: UG# 091593-GW-1456

Responsible party signature

Responsible party (printed)

perprope

U227 N. 215+ St., Omaha, NE 6810 Consultant mailing address or PO Box

Omaha, NE 68110 Consultant city, state, and ZIP code

Consultant signature

Consultant name (printed)

date

The completed form should be mailed to John Fogerty, NDEQ LUST/HA Section, Box 98922, Lincoln, NE 68509-8922 on or before April 10, 2003. The form may also be faxed to (402) 471-2909, with the signed original following by mail.

STATE OF NEBRASKA



FILE GOPY

MAR 4 2003

Michael J. Linder
Director
Suite 400, The Atrium
1200 'N' Street
P.O. Box 98922
Lincoln, Nebraska 68509-8922
Phone (402) 471-2186
FAX (402) 471-2909

DEPARTMENT OF ENVIRONMENTAL QUALITY

Mike Johanns Governor

CERTIFIED - RETURN RECEIPT REQUESTED

Roger and Patricia Houser Medicine Creek Lodge RR 2 Box 88 Cambridge NE 69022

Release Incident File Reactivation Medicine Creek Lodge, Cambridge UG # 091593-GW-1456

Dear Roger and Patricia:

The Department has previously informed you that remedial activities for the above-referenced release would await further action until sufficient resources were available. Such resources are now available, and the Department is activating the file for the purpose of performing a Tier 1 investigation. The investigation results will be used by the Department to determine, based on the risks posed by the release, whether further work will be required or the site should be closed. The purpose of this letter is to inform you, as the owner of the tank system, of your responsibilities in accordance with Neb. Rev. Stat. § 81-15, 124 (Cum. Supp. 1998) for identifying the affected environment and the completion of any remedial actions required by the Department.

Overview of the petroleum release remedial action process

The petroleum release remedial action process, in accordance with Department of Environmental Quality itle 118 - *Ground Water Quality Standards and Use Classification*, Appendix B, includes five main phases. The Department evaluates the results of each phase to determine the next appropriate action, so not all phases may be required at every site. For each phase that is required, the Department will provide additional information detailing the actions that must be performed. The main remedial action phases, in order, are:

- 1. **Tier 1 site investigation** to determine the source areas, potential contaminant receptors, source area and background contaminant levels, and the site's hydrogeologic characteristics.
- 2. **Tier 2 site investigation** (if necessary) to fully delineate soil and ground water contamination as a result of the release and its potential effects.
- 3. Development of a Remedial Action Plan (if necessary) to remove or manage the contamination.
- 4. Cleanup and/or monitoring (if necessary) until the requirements specified in the Remedial Action Plan have been fulfilled.
- 5. Site closure, including removal of monitoring wells and equipment.

Requirements

Based upon the information received by the Department to date, a Tier 1 site investigation is required at this site. Please have your consultant refer to the Department's Risk-Based Corrective Action (RBCA) at Petroleum Release Sites: Tier1/Tier 2 Assessments & Reports (February 2002) environmental guidance document.



On or before April 10, 2003, a completed Tier 1 Pre-Investigation Assessment Work Plan Form (enclosed) must be submitted to this office. You must receive written notification from the Department before any fieldwork can commence.

Any requests for compliance date extensions should be submitted, in writing, to the Department at least 14 days prior to the scheduled compliance date and should include reasons for requesting the extension. Compliance date extensions will be granted only in special circumstances.

Compliance dates for conducting the Tier 1 Pre-Investigation Assessment and any other remedial actions will be established as necessary by the Department. You will be notified in writing of any additional requirements.

Reimbursement of eligible expenses

9

After your deductible has been met, you may be eligible for reimbursement for a portion of your remedial action costs in accordance with Title 200 - Rules and Regulations for Petroleum Release Remedial Action Reimbursement Fund. For more information, contact the Title 200 staff at (402) 471-4230.

Additional information

For your convenience, a list of environmental consultants has been enclosed. Individual consultants who have attended the Department's meetings explaining the Tier 1 site investigation procedures are indicated. The list is not to be considered all-inclusive nor is it an endorsement of those firms that are listed. Additional information or documents can be obtained by contacting me.

Thank you for your cooperation in this matter. If you have any questions or comments, please contact me at (402) 471-4230. Please include the facility name and file number as referenced at the top of this letter in any correspondence to this office from yourself or your consultant.

Sincerely

John K. Fogerty, Geologist

LUST/RA Section
Water Quality Division

Enclosures

tmer Tier 1 Pre-Investigation Assessment Work Plan Form Consulting Firm List

qui

2ase

DOT,

SL# 43-346

(Main Office Use Only)

pernits K

PB. S

FACILITY ID# 8025 JURISDICTION 500

AP8025

20100072817

FLAMMABLE LIQUID STORAGE TANK DIVISION

Report of Suspected Leak

INITIAL MEANS OF DISCOVERY (Circle One)	
1) Product or vapors in structure	10) Product in G.W. monitoring well
2) Product or vapors in sewer system	11) Vapors detected in vapor monitoring
3) Petroleum saturated soils encountered 🕻 📔 🚶 🤘 🖺	12) Leak detection mode activated ATM //
4) Site assessment results indicate contamination	13) Interstitial monitoring-double wall tank or þiþing
5) Tank removed with holes in shell NOV 0 4 1993	14) Leak detector-pressurized piping
6) Petroleum taste in well water	15) Failed tightness test-piping
7) Accumulation of water in tank	16) Hesitation In suction system
9) Failed tightness test-tank DEPARTMENT OF	17) Other
ENVIRONMENTAL QUALIT	"Y
in addition to the initial discovery, list all other characteristic	s from above which suggest a leak.
And the second s	
LOCATION OF SUSPECTED LEAK	
LOCATION OF SUSPECTED LEAK	City AMBRIDGE County FRONTER
101635	Only 277132142 County 7771010-14-271
DATE/TIME OF DISCOVERY	
Hour 1/30 Month Aug Day a	23 Year 1993 Day of week Manual
WHO DISCOVERED SUSPECTED LEAK	Cartified Tank Closer
Name DONALD BURTON Title/Employer	BURTON WELL DRILLING Phone 308) 692-3220
The state of the s	
WHO REPORTED SUSPECTED LEAK TO STATE FIRE M	IARSHAL / DELEGATED AUTHORITY
Name DONALD BURTON Title/Employer	BIRTON WELL DRIVER Phone 308) 692- 3220
• • • • • • • • • • • • • • • • • • • •	•
WHEN REPORTED TO STATE FIRE MARSHAL / DELEG	ATED AUTHORITY
Hour 1/30 Month Aug Day	23 Year 1993 Day of week MONDAY
Investigated by RASMUSSEN 874/	Date 08/23/93 Time 11/0
2nd Investigation	Date Time
ORDERS WRITTENYes _X_No	Fire/Safety hazards existYes No
	Fire/Safety hazards eliminated Yes Yes No
IDERS WRITTEN TO:	Fire/Safety hazard potential Yes No
Name	
Address	
City/State	
HOPE NOTIFIED VALUE NO DATE	Tr. f
NDEC NOTIFIEDYesNo Date	
Person notified at NDEC	Person responding
NDEC release number assigned	
SOURCE OF LEAK IDENTIFIED _K_YesNo	
Product Involved Gasoline	Amount of Loss 2
TOUGHT CONGUE	Amount of Loss
IF NO: List ID#'s of other facilities that may be potential sou	irces of suspected leak
and the state of the radiates married by the potential sou	Established to an include the second
	The state of the s
IF YES:	
Facility name MEDICINE CREEK LODGE	Ownername BOSER Y PATRICIA HOUSER
Facility address BR 2 Bax 88	Owner address RRQ Bax 88
Facility phone # 308) 697 - 3774	City/State CAMBRIDGE, NE
TANK ID#(s) 001	Owner Phone # 308) 697 - 3774
1 V / meneral liquid for the contract of the c	The second secon
DATE REPORTED RECEIVED: 1st Investigation	1 (BANKA HANA BANKA BANKA BANKA BANKA BANKA BANKA BANKA KANKA KANKA KANKA KANKA KANKA KANKA KANKA KANKA KANKA

printed on recycled paper

TANK CLUSURE CHECKLIST

FAC	HITY IDI: 8025 HITY HANE: Medicino Creok DAGE RESS: RR2 BOX 88 Y: CAMBRIDG NE		BASMUSSE N 08/03/193 BURSON WELL LAST USED: 09/94	
PRO	BUCT STORED: TANK IDI KOY) ESSOLINE) ()	
	E OF CLOSURE - (TANK) REMOVAL / IN PLACE - (PIPING) REMOVAL / RCLE ONE)	IN PLACE	(YES NO NY	MA
١.	PERMIT TO CLOSE ON SITE?		96/194	
2.	CERTIFIED CLOSER ON SITE?		V 4	
3.	AREA SECURED FROM PUBLIC AND NO SMOKING SIGNS ARE POSTED?		<u> </u>	desiration continues
4.	TANK INERTED / PURGED (CIRCLE ONE).		<u> </u>	Etransmanner
5.	TANK ATNOSPHERE MONITORED BEFORE AND DURING CLOSURE?			BASSING CONTINUES
	a. Instrument(s) used: TANK TECHTOR - 02	a desa empelancia de societa en de		
6.	18 TANK ATMOSPHERE SAFE FOR CLOSURE? a. Instrument(s) readings < 576 7 m B			distantististististististististististististist
	· · · · · · · · · · · · · · · · · · ·			
ě.	ANY PRODUCT SPILLED DURING EXCAVATION OF TANK / PIPING? a. Approximate amount			-
₿.	ANY CORROSION HOLES PRESENT BEFORE OR AFTER SCRAPING? a. Tank 108's 001-5/0/05			· ·
	b. Piping 101's <u>no tolos</u>			,
9.	GROUND WATER PRESENT IN EXCAVATION? a. Approximate depth to groundwater 40 +			
10.	ANY DISCOLORED SOILS (GREEN-GRAY/BLACK) ENCOUNTERED a. Tank excavation		<u>~</u>	-
	b. Piping excavation		<u></u>	and the same of th
11,	any signs of contamination? a. Visible (Tank 100's) 001 - north end		<u> </u>	***************************************
	b. Oder (Tank ID#'s) 001			
	LABORATORY ANALYSIS OR FIELD ASSESSMENT? (CIRCLE IVYE BONE) PHOTOS TAKEN			
	**************************************	***********		······································
4 D D	ITIONAL CONNENTS: scraping tank backfull war strong volor & discolored	und Pl	voluch line l	acple ll

SITE DRAWING ON BACK - INDICATE NORTH

841

P= Product

F- Fill

V = Vint

SR#	<u>93-346</u>
1R#	Contract Contracts

NEBRASKA STATE FIRE MARSHALS OFFICE FLAMMABLE LIQUID PETROLEUM STORAGE DIVISION SUPPLEMENTAL REPORT

REPORT BY:

REPORT DATE: 08-23-93

DEPUTY GREG RASMUSSEN #8741

INCIDENT DATE: 08-23-93

INCIDENT ADDRESS: RR 2 BOX 88

INCIDENT CITY: CAMBRIDGE

PERSONS MENTIONED IN REPORT:

OWNER/OPERATOR: MEDICINE CREEK LODGE

GREG RASMUSSEN
DONALD BURTON

DEPUTY FLST DIVISION - SFM

CERTIFIED CLOSER/BURTON WELL DRLG

ROGER HOUSER OWNER

COZAD, NE
BARTLEY, NE
CAMBRIDGE, NE

NARRATIVE:

At approximately 1110 hours on August 23, 1993 I arrived at Medicine Creek Lodge, Rural Route 2 in Cambridge, NE, the site of an underground storage tank (UST) removal. Upon arriving I noted that the tank at the site, tank ID# 001 from the registration, had already been excavated. I also noted a strong petroleum odor coming form the area of the excavation. Upon examining the excavation and the tank I noted that there was a check valve and a gate valve in the product line at the tank. i then met with Donald BURTON a certified tank closer for Burton Well Drilling Inc. of Bartley, NE. BURTON advised me that the tank had been backfilled with sand and clay type soil. BURTON then advised me that he had put dry ice into the tank to make the atmosphere of the tank safe for removal when he had arrived a the site. I then asked BURTON if he had tested the atmosphere of the tank to see if the atmosphere was inert. BURTON advised me that he did not have any instrumentation to test the tank atmosphere. I informed BURTON that he would have to have the necessary instrumentation to test the atmosphere of the tanks he was removing at the site from now on. I then tested the atmosphere of the tank using the oxygen (O_0) scale of my Tank Techtor and obtained readings of less than five (5) percent $\bar{0}_{j}$ at the bottom, middle, and top of the tank. The tank was removed from the excavation at approximately 1130 hours on August 23, 1993. After the tank had been removed I made a preliminary examination noting that the tank was covered with rust. As I was scraping the tank I noted that the backfill around the product line bung had a strong petroleum odor and that this backfill was green-gray in color. after scraping the tank I noted heavy corrosion pitting and found five (5) holes in the shell of the tank. Four of the holes were in the south eighteen (18) inches of the tank and one (1) hole was in the north eighteen inches of the tank. All of the holes were in the bottom one (1) foot of the tank. I then had BURTON obtain a soil sample from the native soil, from under where the tank had been, at both ends of the excavation. I allowed these samples to warm as I examined the excavation noting the presence of green-gray soil. I then conducted a headspace Page 2 of 2 5 93-346

analysis of the soil samples using my Tank Techtor. I obtained a reading of fourteen (14) parts per million (ppm) from the sample form under the south end of the tank, and one thousand (1,000) plus ppm from the sample taken form under the north end of the tank. BURTON then advised me that the sample at the south end had been taken about two (2) feet below the bottom of the tank and that the sample at the north end of the tank had been taken about one (1) foot below the bottom of the tank. BURTON then advised me that the top of the tank was two and one-half (2-1/2) to three (3) inches below ground level and that there was about four (4) inches of concrete over the tank. The tank was four (4) feet in diameter by six (6) feet long. I then met with Roger HOUSER, the owner of Medicine Creek Lodge near Cambridge, NE, and informed him of what I had found and of the results of the headspace analysis which I had conducted. I also advised HOUSER that BURTON would be sending soil samples into a laboratory to be tested. HOUSER then advised me that at one time there had been a leak in the product HOUSER was unable to tell me when this Neak had occurred. approximately 1330 hours on August 23, 1993, I left Medio ne Creek Lodge near Cambridge, NE.

This concluded my investigation of an UST removal and suspected leak at Medicine Creek Lodge, Rural Route 2, Box 88, in Cambridge, NE, as of August 23, 1993.

END OF REPORT

931022/GSR/ncm

PATRICIA A HOUSER MEDICINE CREEK LODGE RT 2 BOX 93 CAMBRIDGE NE 69022

CERTIFIED

RE: Petroleum release Facility ID Number: 8025

Facility location:

. CAMBRIDGE

Dear PATRICIA A HOUSER:

The Department has received the site assessment report for the closure of all or part of the underground storage tank system at the above referenced facility. Information in the report indicates that a release of petroleum resulting from the operation of this system has occurred. The purpose of this letter is to inform you, as the owner of the tank system, of your responsibilities in accordance with Neb. Rev. Stat. 81-15, 124 (Supp. 1989) for securing the release, identifying the affected environment, and completion of any remedial action required by this Department.

The Department will require you to perform an investigation and, if necessary, remediation in accordance with Department of Environmental Control Title 118 - Ground Water Quality Standards and Use Classification Appendix A (enclosed). Costs related to the investigation/remediation of this spill may be eligible for reimbursement in accordance with Title 200 - Rules and Regulations for Petroleum Release Remedial Action Fund (enclosed). However, in order to be eligible for reimbursement, work must first receive prior approval by the Department.

Due to the volume of releases of this kind, the Department is currently prioritizing all new spills related to underground storage tank systems. When this site reaches the top of the priority list, a project manager will be assigned, and you or your company will be contacted with requirements to begin an investigation.

During the interim, you may begin an investigation/remediation. However, because it will not be under the direction of the Department, costs incurred will not be eligible for Title 200 reimbursement. You should also be aware that when this site reaches the top of the priority list and a project manager is assigned, the Department may require you to do work in addition to what you have already completed.

If at any time in the future, public safety is threatened by this spill, the State Fire Marshal (402/471-2027) and our office must be notified. Immediate action should be taken to eliminate the problem.

Please feel free to contact me at 402/471-4230 if you have any questions. Also, please contact me if your address or phone number changes. Thank you for your cooperation.

Sincerely,

Nancy Mann, Geologist Ground Water Section Water Quality Division

Enclosures

cc: Clark Conklin

State Fire Marshal

Spill Number:	AP 8025	_ Date Received:	69/15/93
Own Company:			•
Spill Loc:		City:	Cambridge
County:	Frontier	no designation	
e Assert	Remedi	al Action Class: Free Product:	, {
		o Surface Water:	700 pt
- Distan		to Ground Water:	
	Distance to Nea	rest Water Well:	V
Distanance to	Nearest Downgradien	t Drinking Well:	
	Ground Water	Flow Direction:	SE
Un	saturated zone > 50	% Sand & Gravel:	
Materials Rel	eased Include Gasol	ine or Solvents:	
S	oil Protocol Action	Level Exceeded:	

SCORE: 518

Sto CW-



Permis			AP8023
STAFF CODE NEBRASKA DEP PROJECT CODE REFERRAL-DATE	ARTMENT OF ENVIRONMENTA SPILL REPORT FORM	AL CONTROL	COMPUTER PROG COORD PROG SUPV
AG HW WR SW	SPILL NUMBER		
•			
	DATE CLOSED		
REPORTER CODE: 01 - SPILLER 08 - P 02 - NRC 14 - O 06 - NDEC 15 - A	RIV. CITIZEN 16 - EF THER FED. 17 - NE NONYMOUS 18 - OT		
OTHER:			· · · · · · · · · · · · · · · · · · ·
RES	PONSIBLE PARTY INFORMAT	TION	
COMPANY Medicine CAPEK LOC	190 NAME/POSITI	ION Patricia A	Houser
STREET ADDRESS Rt 2 Box 93	city Cam	bridge	
STATE Ne ZIP 69022		<i>'</i>	
	SPILL INFORMATION		
	raft 08-Discharge 11- 09-Fixed Fac. 12-	-From Fire 14-1 -Air Release 15-1	_UST Exempt _and Release
SPILL LOCATION Medicine Creek Lodge,	SW SIde Stowak Lake	J 500 29	TØSN RZEW
SPILL CITY Cambridge.	SPILL COUNTY	Fronties	
(nearest village, town or	city)		
MATERIAL DESCRIPTION: 9950ling			
PRIMARY 01-PCB 0 1/ RIAL 02-Dioxin 0 COL 03-Crude Oil 1 04-Gasoline 1	1-Petro. Solvents 2-Naptha 3-Mineral Spirits	16-Insecticides 17-Fertilizer 18-Metals 19-Acids 20-Org.Solvents	23-Amine 24-Aldehyde 25-Other 26-Unknown
AMOUNT SPILLED 01-Gai 02-Lbs 0	3-Bbis 04-Ton 05-Sheen	06-Unk Qty 07-PPI	M 08-Pint 09-Quart
was Oil Involved? (Y) N U Was Matwaterway Discharge? (Y) N U (Code	~~		
INCLIDENT DESCRIPTION: ALAO 50.00) - al egiplian 1157	Apunded 8/2	23/93 40/0
in tank Visual & olfacto	my evidence of com	taylyatlon. 97	PPM TRPH O RAY @ 10 FT
	/		

VALID WATER CODES: 01-River

01-River 02-Stream 04-Storm Sewer 05-Sanit. Sewer 07-Pond

10-Reservoir 11-Cana!

03-Creek

06-Lake

·08-Ditch 09-Ground Water

NOTIFICATIONS: (Name, Organization, Date, Time, Phone Number) ADDITIONAL INFORMATION: _____ 8025 SFM ID: Reporting Date: Facility Name: Correspondence Contact: Street: City: St: Zip: Longitude: 1000 13 5111 Latitude: Method: Accuracy: Point Description:



BURTON WELL DRILLING

P. O. BOX 123

PHONE (308) 692-3220

BARTLEY, NEBRASKA 69020



MEDICINE CREEK LODGE
CLOSURE ASSESSMENT
CAMBRIDGE, NE 69022
AUGUST 23, 1993

RECEIVED

SEP 1 5 1993

DEPARTMENT OF ENVIRONMENTAL QUALITY APPROVED

20100072811



BURTON WELL DRILLING

P. O. BOX 123

PHONE (308) 692-3220

BARTLEY, NEBRASKA 69020

August 30, 1993

Nebraska State Fire Marshal Flammable Liquid Storage Division 246 South 14 Street Lincoln, NE 68508-1804

To: Nebraska State Fire Marshal

From: Donald D. Burton, Burton Well Drilling, Inc.

RE: Submittal of Closure Assessment Report on Medicine Creek Lodge, NE; Facility ID #8025

Enclosed for submittal to your department is the closure assessment report on Medicine Creek Lodge, Cambridge, NE.

If you have any questions or comments, please feel free to contact me at the office.

Sincerely,

Donald D. Burton

Burton Well Drilling, Inc.

is

NEBRASKA STATE FIRE MARSHAL FLAMMABLE LIQUID STORAGE DIVISION CLOSURE ASSESSMENT REPORT



CERTIFICATION OF COMPLIANCE

I CERTIFY THAT THIS CLOSURE WAS CONDUCTED IN ACCORDANCE WITH TITLE 159, RULES AND REGULATIONS FOR UNDERGROUND STORAGE TANKS, REGARDING PERMANENT CLOSURE AND CHANGE-IN-SERVICE AND THAT ALL THE INFORMATION PRESENTED HEREIN IS CORRECT AND ACCURATE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

Thedicine creek Lodge

____ DATE: <u>8-23-93</u>

OWNER/OPERATOR

DATE: 8/30/93

CERTIFIED CLOSURE INDIVIDUAL

TANK CLOSURE CHECKLIST

		ERIAL USED TO FI	ILL	()
		YES	NO	NW
۱.	PERMIT TO CLOSE ON SITE?			
2.	CERTIFIED CLOSER ON S!TE?	<u> </u>		
3.	AREA SECURED FROM PUBLIC AND NO SMOKING SIGNS POSTED?	V		
٤.	TANK INERTED / PURGED (CIRCLE ONE).	V		
5.		V		
	a. Instrument(s) used: <u>tank Protor to effor</u>			1 114 2 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6.	IS TANK ATMOSPHERE SAFE FOR CLOSURE? a.Instrument(s) readings		The first and the second secon	
7.	ANY PRODUCT SPILLED DURING EXCAVATION OF TANK / PIPING? a. Approximate amount			
3.	ANY CORROSION HOLES PRESENT BEFORE OR AFTER SCRAPING?	V	7	
	a. Tank ID#'s b. Piping ID#'s			
9.	GROUND WATER PRESENT IN EXCAVATION? a. Approximate depth to groundwater36			
10.	ANY DISCOLORED SOILS (GREEN-GRAY/GLACK) ENCOUNTERED?	v		
	a. Tank excavation (tank ID#) b. Piping excavation (tank ID#)	The state of the s	The second secon	and dereganization
11.	ANY SIGNS OF CONTAMINATION?	<u>i</u>		
	a. Visible (Tank ID#'s) <u>V&S</u> b. Odor (Tank ID#'s) <u>V&S</u>	V		
12.	WAS A SITE ASSESSMENT PERFORMED?	1		
	LABORATORY ANALYSIS OR FIELD ASSESSMENT? (CIRCLE TYPE DONE) IF FIELD ANALYSIS, INSTRUMENT USED			
13.	PHOTOS TAKEN?	1/		
14.	WAS OVEREXCAVATION PERFORMED?	V		

SAMPLING RESULTS

TANK: COLLECT AND ANALYZE TWO SAMPLES PER TANK. INDICATE THE LOCATIONS WHERE THE SAMPLES WERE COLLECTED AND THEIR RESPECTIVE IDENTIFICATION NUMBERS ON THE SITE PLAN. IN THE TABLE BELOW PLACE THE RESULTS OF SAMPLING IN THE TANK NUMBER COLUMNS. INDICATE THE DEPTH AT WHICH EACH SAMPLE WAS TAKEN IN THE DEPTH COLUMN.

	TANK #		1	2		3		4		5			6	7		8	
	SAUPLE	TEST RESULTS	BEPTH	TEST RESULTS	DEPTB	TEST BESHLTS	BEPTN	TEST Results	DEPT#	TEST RESULTS	DEPTH	TEST RESULTS	DEPTR	TEST Results	DEPTH	TEST RESULTS	DEPIH
302	1 T	970	10.												**************		
302 303	21	13	10,										ALINEA - WARRING COLOR				
304	3 T	180	10.													and the second s	
	4 T															A A E 1985 A A M. A M. A M. A M. A M. A M	THE SHAPE OF THE S
	5 T																
1	• т																
	8T							İ									
	9 T																
	10T														and the second s	***************************************	

CHECK HERE IF DISPENSER IS <u>directly</u> above tank - no additional sampling is required for product lines

LINES: INDICATE WHERE EACH SAMPLE WAS TAKEN AND THEIR RESPECTIVE IDENTIFICATION NUMBER ON THE SITE PLAN.

LINE #		1	2		3		4		5			6	7		8	anakatangka garang t
SAUPLE	TEST RESULTS	BEPTR	TEST BESULTS	DEPTH	TEST RESULTS	DEPTH	TEST RESULTS	DEPTH	TEST RESULTS	DEPTH	TEST RESULTS	BEPTH	TEST RESULTS	DEPTH	TEST RESULTS	DEPIN
1_														***************************************	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
															-	
31																
41									<u> </u>	L						
5L																
6L																
7L																
8 L																

DISPENSER ISLANDS: INDICATE WHERE EACH SAMPLE WAS TAKEN AND THEIR RESPECTIVE IDENTIFICATION NUMBER ON THE SITE PLAN.

DISPENSER	1		2		3		4		5			6	7		8	
SARPLE	TEST Results	DEPTH	TEST RESULTS	DEPTH	TEST BESULTS	DEPTH	TEST RESULTS	DEPIH	TEST RESULTS	DEPTH	TEST RESULTS	DEPIH	TEST RESULTS	BEPTH	TEST RESULTS	DEPTH
10			and a second	~~440\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	and the state of t										in an in an ini ang an alam da in an	
20																
3 D															***************************************	
	and the second state of the second se		L			<u> </u>						L		<u> </u>		

FACILITY ID# <u>8025</u> CONTRACTOR # <u>2437</u>

Lank showed signs of leakage or spillage at N. end of tank. When lifted out holes were found in the lottom of tank approx. Is in diameter. I respected diet down to approx. 10' and clay based soil still had a grey lober ? odor.

At 10:50 AM. soil samples were taken from the mature soil at each end and middle of tank location. Soil samples were sent to Platte Valley Late in Gilbon, No. for analysis, using the EPA method TRPH 418.1.

Loil sample results from Platte Valley Lab. Mailed to Buston Well Orilling office 8/30/93 showed the attached results.

Legal location of tank location is: Frontier Co., Sec. 23 Township P5, Range 26, SE gt.

Manned, edited, and published by the Geological Survey as part of the Department of the interior program


40°22'30" K

Mediana Crock Tody

FACILITY ID# 8025 CONTRACTOR # 2437

DATE OF CLOSURE: 8-23-43

LAYOUT OF THE TANK SYSTEM (TANK AND PRODUCT LINES) AND PLACEMENT OF EXCAVATION AND DISPENSER(S) LOCATION. THE SITE PLAN MUST BE APPROXIMATELY TO SCALE, INCLUDING DISTANCES AND THE NORTH ARROW. ALSO SHOW THE TANKS RELATIONSHIP TO PERMANENT OBJECTS.



CLOSURE ASSESSMENT ANALYSIS REQUEST CHAIN OF CUSTODY SHEET


CONTRAC	TOR:_	Bu	nton	Well	Drike	ns	DATE: FACILITY ID#: 8025								
LICENSE	LICENSE #: 2437					RE:									
ADDRESS	: <u>B</u> ø	x /2	9 Ba	rthey 1	VE 6902	<u>.</u> 6	ADDRESS	S:							
				ve			FACILIT	Y CON	TACT:						
				12 - 3			PHONE N				•				
					S (LIST OT	HER IT	EMS):								_
LAB ID#	FIE		DATE	TIME	TYPE*	PRES	ERVATIVE	918-1							
302	型の	NE	8-23-9	10:50	501			X							
<i>3</i> 03	#1B		8-23-93	10:50	Soil			ベ							
304	#3		8-23-93	10:50 AM	soil			X							
SPECIAL H	SPECIAL HANDLING AND/OR STORAGE:														
SAMPLE COLLECTOR: Dave Bunton NAME (PRINT) SIGNATURE Date Time PM															
O/(#/ EE 00				NAME (PRI	NT)				SIGNAT	URE			DATE	TIME	PM
COLLABORA	TIVE L	AB (IF	REQUIRE	1):											
COLLABORA Lab Id			FROM Bove	TO LAB N	AME:				· •)ATE SENT			
					·					a. es. a rep a usatinis					

					CHAI	N OF	сиѕтог	ΟY							
RECEIVED (SIGNAJU				DATE	/TIME		NQUISHED E SIGNATURE,		in the second property of the second property				DATE	/TIME	reduce a view of your desire. And of
Steve Spellman 8/24/93															
					,					F-445-144-144-144-144-144-144-144-144-144					
A 100 A															
TYPE* - IN	TYPE* - INDICATE WATER, SOIL, SLUDGE, ECT. DISTRIBUTION: ORIGINAL ACCOMPANIES SHIPMENT														

SEND COMPLETED TO: FLAMMABLE LIQUID PETROLEUM STORAGE DIVISION

246 SOUTH 14TH STREET LINCOLN, NE 68508

PHONE# (402) 471-9465 FAX# (402) 471-3118



Burton Well Drilling, Inc

Attn: Don / Dave

PO Box 123

Bartley

NE 69020

Analytical Report

Date: 8/26/93

Project 8025

Description

Sample Type Soil

		The second secon	31		1	4.,		
				TRPH		Paint	Total	Flash
	Lab No.	Sample ID	Units	418.1	pH	Fige	Lead	Point
APPROVED STREET, STREE	302	# 2B NE	mg/kg	970				
CONTRACTOR	303	# 18	mg/kg	13				the contract of the contract o
SWEWS SANSONNE SPORT	304	# 3 BY PUMP 15' N	mg/kg	180		TOTAL SALES AND		and the second second

TRPH Detection Limits:

Soil 2 mg/kg Water 1 mg/l

SlowSpellman

NEBRASKA STATE FIRE MARSHAL FLAMMABLE LIQUID STORAGE TANK DIVISION


246 South 14th Street (402) 471-9485

Lincoln, NE 68508-1804

FACILITY ID#	8025
Installation of	ne lander saller de la region de la
	Clarana Tanba

MEDICINE CREEK LODGE ROUTE 2. BOX 93

Closure of ______ (ONE) Underground Storage Tanks LOCATION: 69022 CAMBRIDGE. NE



Permit to Install/Close UST's

This office has review	ed your material	s submitted to	this office fo	r compliance v	ilth the Nebraska	a Fire Safety Regi	ulations and
Title 159, Rules and F							
on elte by the certifle		WHICH SEE SEE SEE SEE SEE	SAN AND SERVICE	THE SECTION OF THE SE	Maria de la companya		al strategic and the same

\bigcap	Installation Approved
	(See Remarks)



Closure Approved (See Remarks)

IARKS:

- This permit is for closure only. A separate permit is required for the installation of new aboveground tanks.
- Tanks removed from the ground shall be stored in a secure location inaccessible to the general public. TITLE 159
- If a closure assessment is required, your closure assessment report shall be submitted to the State Fire Marshal (Lincoln Office) by August
- If contamination is present in the excavation the State Fire Marshal and the Department of Environmental Quality must be notified within 24 hours.
- Notify Deputy Greg Rasmussen 48 hours prior to the closure at 308-784-4444.
- The State Fire Marshal must be contacted prior to the re-use of this underground TITLE 153, CHAPTER 17, & TITLE 159, CHAPTER 4

8-16-93 Extension granted as reguested by Dave Butter to Sept 7, 1993. nom

CC: NDEO

CONTACT THIS OFFICE FOR AN INSPECTION AT LEAST 24 HOURS PRIOR TO PRE-INSTALLATION AIR PRESSURE TEST ON TANK(S). FLAMMABLE LIQUID STORAGE TANK DIVISION, (402)-471,9465

APPROVED BY:

CLARK CONKLIN, MANAGER FLAMMABLE LIQUID STORAGE DIVISION

FLST.15

NEBRASKA STATE FIRE MARSHAL FLAMMABLE LIQUID STORAGE TANK DIVISION

246 South 14th Street Lincoln, NE 68508-1804

(402) 471-9465

FACILITY ID#802	5				
Installation of					
Underground Storage Tanks					
Closure of1(ONE)				
Underground Storage Tanks					

LOCATION:

MEDICINE CREEK LODGE ROUTE 2, BOX 93

CAMBRIDGE, NE 69022

DATE: TO:

JUNE 24, 1993 BURTON WELL DRILLING P.O. BOX 123 NE 69020 BARTLEY.

CL#93189

Permit to Install/Close UST's

This office has reviewed your materials submitted to this office for compliance with the Nebraska Fire Safety Regulations	and
Title 159, Rules and Regulations Concerning Underground Storage Tanks in the State of Nebraska. This permit must be	kept
on site by the ceritified contractor.	

	1	Installation Approved
1	ノ	(See Remarks)

	Resubmit for Approva
\bigcup	(See Remarks)

XX	Closure Approved
	Closure Approved (See Remarks)

REMARKS:

- 1. This permit is for closure only. A separate permit is required for the installation of new aboveground tanks.
- Tanks removed from the ground shall be stored in a secure location inaccessible to the general public. TITLE 159
- 3. If a closure assessment is required, your closure assessment report shall be submitted to the State Fire Marshal (Lincoln Office) by August 16, 1993.
- 4. If contamination is present in the excavation the State Fire Marshal and the Department of Environmental Quality must be notified within 24 hours.
- 5. Notify Deputy Greg Rasmussen 48 hours prior to the closure at 308-784-4444.
- The State Fire Marshal must be contacted prior to the re-use of this underground 6. storage tank. TITLE 153, CHAPTER 17, & TITLE 159, CHAPTER 4

CC: NDEQ

CONTACT THIS OFFICE FOR AN INSPECTION AT LEAST 24 HOURS PRIOR TO PRE-INSTALLATION AIR PRESSURE TEST ON TANK(S). FLAMMABLE LIQUID STORAGE TANK DIVISION, (402)-471;9465

APPROVED BY:

NEBRASKA STATE FIRE MARSHAL FLAMMABLE LIQUID STORAGE TANK DIVISION

246 South 14th Street Lincoln, NE 68508-1804 (402) 471-9465



JUN 1: 1 1993

SOV INK

Application for Permit to Permanently Close Tank

TANK OWNERSHIP Name of Owner/Operator	TANK LOCATION Name of Business/Company
Patricia A. Houser	Medicine Creek Lodge
Street	I Cirnot
Route 2 Box 93	Route 2 Box 93 City State Zip
Cambridge 69022 Frontier	Cambridge, NF. 69022 Telephone
(308) 697-3774 STATUS	(308) 697-3774 DETANKS
Are tanks registered with the State Fire Marshal's Office? X Yes No	
If yes, give Facility ID# 8025	If no, give year of last use
TE: If tanks are not registered or if registration fees are past due, civil penalties may be considered against the owner prior to approval of this permit application.	
Will a closure assessment be performed in accordance with Title 159? X Yes LI No If yes, what other contractors or laboratories will be involved?	
If no, check reasons for not performing site assessment. NDEC Ordered Investigation On-going	
Tanks taken out of service prior to July 17, 1986 and property owner never used tanks	
LICENSED CLOSURE CONTRACTOR	GERTIFIED CLOSURE INDIVIDUAL
Burton Well Drilling	Dave Burton (Donald & David)
P.O. Box 123	2437
Bartley, NE. 69020	11-19-95
308, 692-3220 CL 9318 9	308) 692-3220 PM
Projected Tank Closure Date Not Definate ASAP	Number of Tanks Being Closed / 11/92
List Tank ID#'s 01 - unknown gas METHOD OF CLOSURE	
Tank: X Bemoval Closure in place Will these tanks be replaced? X Yes I No Cl Underground L Aboveground Will piping be replaced? Yes I No Will tanks be replaced with new tanks? Yes I No Cl Underground X Aboveground	
Will tanks be emptied and cleaned by removing all liquids and accumulated sludge? X Yes 11No If yes, will all liquids and sludges be recycled or disposed of in accordance with all state and local regulations? X Yes 11No	
If Earlk(s) are removed, indicate storage location or final destiny. Not certain Rearest Scrap yard	
If tank(s) are closed in place, indicate type of inert material used.	
All tanks must be closed in accordance with Title 159, State Fire Marshal Underground Storage Tank Rules & Regulations!	
Application Submitted by Patricia A.	Housev
Vatricia a.	Houser 6-16-93 Signature) (hate

Jus-5-9-94