

2 Hurt At Dam On Friday Recovering

Howard Hord, who was seriously injured yesterday morning when struck by pieces of a fallen agitator-mixer at intake tower number three, was reported as resting easily and to be slightly improved this morning.

H. O. Wall, who sustained a fractured shoulder and back bruises, was also reported to be resting easily.

Two others, employes of Six Companies Inc., were slightly injured at the time of the accident, but so slightly that their names could not be learned.

The accident occurred when an agitator-mixer, weighing approximately ten tons, slipped from the landing platform above the intake tower as it was being transferred from number ten calbeway to number two derrick. The agitator, after becoming loosened, rolled off the platform, down the side of the cliff, and into the intake tower. The fact that Hord and Wall were working under the heavy net of 1¼ inch reinforcing steel saved them from certain death.