RECLAMATION

Managing Water in the West

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION

Match Line

Pumping Plant # 1

Pumping Plant # 2

Pumping Plant # 3

Wellton

Tacna

Mohawk Canal

Dome Canal

Main Consolidated Canal

Texas Hill Canal

Township 6 South - Gila and Salt River Meridian

Range 21 West - Gila and Salt River Meridian

0 0.5 1 2 3
Miles

Legend

- Depth to Groundwater Contours
- 12.3 Observation Well (Reading (ft.))
- Drainage Well
- Canal
- Drain
- Public Lands Survey Section Line
- Escarpment
- Major Road
- Road

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION

WELLTON-MOHAWK VALLEY
ARIZONA

DEPTH TO GROUNDWATER
October 2015

DATA: WMIDD
DRAWN: T. STAGGS
CHECKED: B. GREER
APPROVED: J. NEMETH

YAOGIS2015-0137