December 2013 Construction Photos

Baldwin Creek Fish Barrier: The contractor is installing guardrail for the fish barrier weir access road turnaround.

Baldwin Creek Fish Barrier: The contractor is broadcasting hydro-seed on the north embankment of the barrier weir.

Baldwin Creek Fish Barrier: The contractor installing stormwater prevention best management practices on the new access road slope.