Part 7.13

Typical Images of Concession Areas at Lake Berryessa

The following Appendix includes typical images of five Concession Areas at Lake Berryessa. This appendix is not intended to be an exhaustive or comprehensive coverage of conditions, facilities, or hazards at Lake Berryessa, but is intended to provide illustration of the typical conditions in the five sites under consideration.

Contents

Page

Part 7.13	
Typical Images of Concession Areas at Lake Berryessa	
Putah Canyon	
Monticello Shores	
Berryessa Point	
Spanish Flat	
Steele Canyon	

Putah Canyon



Figure 7.13 - 1: Typical Road Surface at Putah Canyon



Figure 7.13 - 2: Elevated View of Putah Canyon



Figure 7.13 - 3: Entrance to Putah Canyon with Pre Existing Facilities (Fence and Gates) and Reclamation Personal Property (Entrance Station and Signs)



Figure 7.13 - 4: Entrance to Putah Canyon with Pre Existing Facilities (Fire Gates) and Reclamation Personal Property (Signs)



Figure 7.13 - 5: View of Launch Ramp Parking with Underground Storage Tank Remediation Facilities



Figure 7.13 - 6: Pre-Existing Facilities (Rock Walls)




Figure 7.13 - 7: View of Launch Ramp with Reclamation Personal Property (Launching Deck)



Figure 7.13 - 8: View of Pre-Existing Facilities (Retaining Walls)



Figure 7.13 - 9: View of Reclamation Improvements (Vault Toilet and Day Use Area)




Figure 7.13 - 10: View of Pre-Existing Facilities (Retaining Walls) and Reclamation Personal Property (Tables, Grills and Fire Rings)



Figure 7.13 - 11: View of Reclamation Personal Property (Tables and Grills)




Figure 7.13 - 12: View of Pre-Existing Facilities (Concrete Stairs)




Figure 7.13 - 13: View of Lake from Putah Canyon



Figure 7.13 - 14: View of Pre-Existing Facilities (Secondary Boat Launch)




Figure 7.13 - 15: View of Pre-Existing Facilities (Concrete Pads)



Figure 7.13 - 16: View of Pre-Existing Facilities (Foundation Concrete Pads)



Figure 7.13 - 17: View of Pre-Existing Facilities (Stairs Retaining Walls)



Figure 7.13 - 18: View of Pre-Existing Facilities (Retaining Wall)



Figure 7.13 - 19: View of Reclamation Personal Property (Tables and Fire Rings) in Camping/Day Use Area



Figure 7.13 - 20: View of Reclamation Personal Property (Tables and Fire Rings) in Camping/Day Use Area

Monticello Shores



Figure 7.13 - 21: Typical Road Surface at Monticello Shores



Figure 7.13 - 22: Typical View in Monticello Shores



Figure 7.13 - 23: Open Area in Monticello Shores



Figure 7.13 - 24: Typical View of Monticello Shores



Figure 7.13 - 25: Downed Tree at Monticello Shores



Figure 7.13 - 26: View of Ore-Existing Facilities (Retaining Wall)



Figure 7.13 - 27: View of Pre-Existing Facilities (Wires)



Figure 7.13 - 28: View of Pre-Existing Facilities (Light Poles, Wires)




Figure 7.13 - 29: Road in Monticello Shores




Figure 7.13 - 30: View of Pre-Existing Facilities (Retaining Wall)



Figure 7.13 - 31: View of Pre-Existing Facilities (Retaining Wall)



Figure 7.13 - 32: View of the Lake through Oak Trees in Monticello Shores

Berryessa Point



Figure 7.13 - 33: View of Peninsula from Northern Part of Berryessa Point



Figure 7.13 - 34: View of Pre-Existing Facilities (Wires)



Figure 7.13 - 35: Former Trailer Site at Berryessa Point



Figure 7.13 - 36: Typical Road Surfaces at Berryessa Point



Figure 7.13 - 37: View of Pre-Existing Facilities (Retaining Wall on Peninsula in Rescinded Area)



Figure 7.13 - 38: View of Pre-Existing Facilities (Light Pole and Wires)



Figure 7.13 - 39: View of Pre-Existing Facilities (Retaining Wall)




Figure 7.13 - 40: View of Pre-Existing Facilities (Poles and Light)




Figure 7.13 - 41: View of Pre-Existing Facilities (Retaining Wall)




Figure 7.13 - 42: View of Pre-Existing Facilities (Retaining Wall)



Figure 7.13 - 43: View of Lake from Berryessa Point

Spanish Flat



Figure 7.13 - 44: Former Trailer Terraces at Spanish Flat



Figure 7.13 - 45: Typical Road Surface and Trailer Terraces at Spanish Flat



Figure 7.13 - 46: Current Camp Sites and Day Use Area at Spanish Flat



Figure 7.13 - 47: Lake View through Oak Trees at Spanish Flat



Figure 7.13 - 48: View of Reclamation Improvement (RV Dump Station)



Figure 7.13 - 49: View of Reclamation Improvement (Water Spigots)



Figure 7.13 - 50: View of Reclamation Personal Property (Tables, Grills and Fire Rings) and Pre-Existing Facilities (Fence)



Figure 7.13 - 51: View of Reclamation Personal Property (Entrance Station) and Pre-Existing Facilities (Fence and Gates)



Figure 7.13 - 52: View of Day Use Area with Reclamation Personal Property (Tables, Grills, Fire Rings and Sign)



Figure 7.13 - 53 View of Camping Area (L) with Reclamation Personal Property (Tables, Grills, Fire Rings)



Figure 7.13 - 54: View of Former Boat Ramp Location



Figure 7.13 - 55: View of Pre-Existing Facilities (Poles/Wires)




Figure 7.13 - 56: Camping Area Reclamation Personal Property (Table, Grill)

Steele Canyon



Figure 7.13 - 57: Large Open Area at Steele Canyon



Figure 7.13 - 58: Former Trailer Terraces at Steele Canyon with Shade Trees



Figure 7.13 - 59: View of Launch Ramp with Reclamation Personal Property (Launch Docks)



Figure 7.13 - 60: Entrance to Steele Canyon



Figure 7.13 - 61: Entrance for Steele Canyon with Reclamation Personal Property (Entrance Station) and Pre-Existing Facility (Gates)



Figure 7.13 - 62: View of Reclamation Improvements (RV Dump Station)




Figure 7.13 - 63: View of Reclamation Improvements (Vault Toilet)



Figure 7.13 - 64: View of Pre-Existing Facilities (Billboard)



Figure 7.13 - 65: View of Parking Area with Pre-Existing Facilities (Fence and Gate)




Figure 7.13 - 66: View of Pre-Existing Facility (Stairs)



Figure 7.13 - 67: View of Lake with Pre-Existing Facilities (Retaining Walls)




Figure 7.13 - 68: View of Reclamation Personal Property (Tables, Grills, Fire Rings and Pre-Existing Facilities (Light Pole, and Wires, Fence)



Figure 7.13 - 69: View of Camping Area with Reclamation Personal Property (Table and Grill)



Figure 7.13 - 70: View of Pre-Existing Facilities (Stairs, Bollards Poles, Wires)



Figure 7.13 - 71: View of Ramp with Reclamation Personal Property (Launch Docks)



Figure 7.13 - 72: View of Pre-Existing Facilities (Poles, Wires, Old Pump Cut off Switch)