

COLLINSVILLE BOTTOM ON THE SACRAMENTO RIVER
WATER QUALITY REPORT

MAY 2011

RUN DATE: July 12, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 155 | 139 | 148 |
| 2 | 158 | 149 | 152 |
| 3 | 155 | 145 | 150 |
| 4 | 156 | 142 | 147 |
| 5 | 158 | 145 | 148 |
| 6 | 153 | 141 | 147 |
| 7 | 166 | 136 | 148 |
| 8 | 157 | 131 | 143 |
| 9 | 144 | 131 | 136 |
| 10 | 147 | 135 | 138 |
| 11 | 154 | 131 | 141 |
| 12 | 156 | 115 | 134 |
| 13 | 139 | 118 | 125 |
| 14 | 134 | 117 | 125 |
| 15 | 133 | 118 | 124 |
| 16 | 129 | 118 | 123 |
| 17 | 135 | 117 | 124 |
| 18 | 127 | 116 | 121 |
| 19 | 125 | 118 | 121 |
| 20 | 124 | 117 | 121 |
| 21 | 126 | 119 | 122 |
| 22 | 128 | 123 | 125 |
| 23 | 137 | 120 | 126 |
| 24 | 136 | 119 | 127 |
| 25 | 136 | 124 | 131 |
| 26 | 136 | 128 | 132 |
| 27 | 134 | 121 | 127 |
| 28 | 130 | 123 | 126 |
| 29 | 129 | 125 | 127 |
| 30 | 134 | 129 | 131 |
| 31 | 139 | 133 | 137 |

Comments:

0 reading indicates that the station was out of service.