

COLLINSVILLE BOTTOM ON THE SACRAMENTO RIVER
WATER QUALITY REPORT

MAY 2017

RUN DATE: June 5, 2017

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 140 | 96 | 111 |
| 2 | 145 | 99 | 110 |
| 3 | 119 | 99 | 106 |
| 4 | 118 | 101 | 108 |
| 5 | 165 | 107 | 124 |
| 6 | 237 | 109 | 126 |
| 7 | 131 | 117 | 123 |
| 8 | 191 | 123 | 136 |
| 9 | 157 | 124 | 136 |
| 10 | 204 | 125 | 144 |
| 11 | 168 | 132 | 141 |
| 12 | 181 | 131 | 147 |
| 13 | 155 | 112 | 139 |
| 14 | 150 | 107 | 125 |
| 15 | 146 | 103 | 119 |
| 16 | 143 | 104 | 122 |
| 17 | 169 | 101 | 122 |
| 18 | 170 | 99 | 118 |
| 19 | 172 | 102 | 122 |
| 20 | 184 | 103 | 126 |
| 21 | 221 | 100 | 134 |
| 22 | 176 | 101 | 126 |
| 23 | 166 | 103 | 128 |
| 24 | 160 | 106 | 131 |
| 25 | 168 | 103 | 130 |
| 26 | 171 | 104 | 129 |
| 27 | 166 | 105 | 131 |
| 28 | 164 | 108 | 133 |
| 29 | 161 | 107 | 132 |
| 30 | 169 | 107 | 134 |
| 31 | 163 | 109 | 131 |

Comments:

0 reading indicates that the station was out of service.