

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 20
WATER QUALITY REPORT

MAY 2009

RUN DATE: June 3, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 640 | 574 | 604 | 389 |
| 2 | 654 | 602 | 621 | 400 |
| 3 | 633 | 591 | 613 | 395 |
| 4 | 638 | 580 | 602 | 388 |
| 5 | 654 | 582 | 608 | 392 |
| 6 | 627 | 562 | 597 | 385 |
| 7 | 609 | 534 | 567 | 366 |
| 8 | 625 | 498 | 557 | 360 |
| 9 | 623 | 545 | 576 | 372 |
| 10 | 636 | 571 | 591 | 381 |
| 11 | 618 | 570 | 589 | 380 |
| 12 | 597 | 570 | 584 | 377 |
| 13 | 601 | 531 | 562 | 363 |
| 14 | 622 | 537 | 592 | 382 |
| 15 | 641 | 537 | 591 | 381 |
| 16 | 588 | 522 | 551 | 357 |
| 17 | 575 | 511 | 535 | 347 |
| 18 | 598 | 490 | 516 | 335 |
| 19 | 571 | 493 | 517 | 336 |
| 20 | 566 | 517 | 546 | 353 |
| 21 | 581 | 515 | 545 | 353 |
| 22 | 618 | 565 | 587 | 379 |
| 23 | 612 | 555 | 593 | 382 |
| 24 | 615 | 587 | 597 | 385 |
| 25 | 605 | 546 | 577 | 373 |
| 26 | 607 | 533 | 578 | 373 |
| 27 | 578 | 550 | 560 | 362 |
| 28 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 |
| TOTAL | | | 15,556 | |

Comments:

0 reading indicates that the station was out of service.