

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 20
WATER QUALITY REPORT

MAY 2012

RUN DATE: June 22, 2012

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 627 | 590 | 612 | 394 |
| 2 | 695 | 596 | 645 | 415 |
| 3 | 690 | 628 | 651 | 418 |
| 4 | 714 | 665 | 693 | 444 |
| 5 | 697 | 662 | 685 | 439 |
| 6 | 653 | 610 | 622 | 400 |
| 7 | 615 | 606 | 611 | 394 |
| 8 | 639 | 615 | 623 | 401 |
| 9 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 | 0 |
| 12 | 524 | 524 | 524 | 340 |
| 13 | 539 | 525 | 530 | 344 |
| 14 | 538 | 515 | 525 | 340 |
| 15 | 564 | 528 | 545 | 353 |
| 16 | 585 | 551 | 570 | 368 |
| 17 | 565 | 471 | 518 | 336 |
| 18 | 491 | 475 | 481 | 313 |
| 19 | 485 | 438 | 459 | 300 |
| 20 | 482 | 435 | 452 | 295 |
| 21 | 489 | 467 | 477 | 311 |
| 22 | 514 | 471 | 495 | 322 |
| 23 | 523 | 490 | 507 | 329 |
| 24 | 511 | 489 | 501 | 326 |
| 25 | 517 | 502 | 508 | 330 |
| 26 | 517 | 491 | 501 | 326 |
| 27 | 526 | 490 | 510 | 331 |
| 28 | 498 | 487 | 490 | 319 |
| 29 | 517 | 494 | 505 | 328 |
| 30 | 495 | 464 | 482 | 314 |
| 31 | 464 | 428 | 443 | 290 |
| TOTAL | | | 15,165 | |

Comments:

0 reading indicates that the station was out of service.