

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 20
WATER QUALITY REPORT

JUNE 2014

RUN DATE: July 31, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 698 | 683 | 693 | 444 |
| 2 | 696 | 667 | 677 | 434 |
| 3 | 676 | 668 | 672 | 431 |
| 4 | 679 | 655 | 668 | 429 |
| 5 | 656 | 649 | 652 | 419 |
| 6 | 653 | 636 | 643 | 413 |
| 7 | 666 | 642 | 653 | 420 |
| 8 | 668 | 655 | 661 | 424 |
| 9 | 678 | 663 | 671 | 431 |
| 10 | 727 | 673 | 713 | 457 |
| 11 | 711 | 686 | 699 | 448 |
| 12 | 721 | 696 | 710 | 455 |
| 13 | 808 | 712 | 749 | 479 |
| 14 | 729 | 654 | 698 | 447 |
| 15 | 717 | 684 | 709 | 454 |
| 16 | 739 | 716 | 730 | 467 |
| 17 | 749 | 737 | 746 | 477 |
| 18 | 757 | 745 | 751 | 480 |
| 19 | 761 | 749 | 754 | 482 |
| 20 | 790 | 761 | 771 | 492 |
| 21 | 790 | 739 | 769 | 491 |
| 22 | 742 | 699 | 732 | 468 |
| 23 | 741 | 726 | 732 | 468 |
| 24 | 747 | 741 | 745 | 476 |
| 25 | 744 | 736 | 740 | 473 |
| 26 | 743 | 735 | 738 | 472 |
| 27 | 742 | 718 | 726 | 465 |
| 28 | 722 | 717 | 720 | 461 |
| 29 | 721 | 716 | 719 | 460 |
| 30 | 726 | 716 | 721 | 462 |
| TOTAL | | | 21,362 | |

Comments:

0 reading indicates that the station was out of service.