

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 20
WATER QUALITY REPORT

DECEMBER 2011

RUN DATE: February 2, 2012

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|------|-----|--------------|-----|
| 1 | 400 | 381 | 388 | 256 |
| 2 | 394 | 386 | 390 | 257 |
| 3 | 437 | 390 | 410 | 269 |
| 4 | 490 | 440 | 471 | 307 |
| 5 | 490 | 453 | 480 | 313 |
| 6 | 462 | 433 | 445 | 291 |
| 7 | 487 | 427 | 449 | 293 |
| 8 | 498 | 487 | 493 | 321 |
| 9 | 486 | 465 | 481 | 313 |
| 10 | 478 | 452 | 470 | 306 |
| 11 | 478 | 463 | 469 | 306 |
| 12 | 483 | 478 | 480 | 313 |
| 13 | 484 | 471 | 477 | 311 |
| 14 | 474 | 460 | 467 | 305 |
| 15 | 461 | 453 | 458 | 299 |
| 16 | 464 | 454 | 458 | 299 |
| 17 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 |
| TOTAL | | | 7,286 | |

Comments:

0 reading indicates that the station was out of service.