

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 21
WATER QUALITY REPORT

JUNE 2014

RUN DATE: July 31, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 672 | 652 | 662 | 425 |
| 2 | 668 | 640 | 654 | 420 |
| 3 | 648 | 633 | 641 | 412 |
| 4 | 650 | 635 | 642 | 413 |
| 5 | 646 | 618 | 628 | 404 |
| 6 | 626 | 609 | 619 | 399 |
| 7 | 632 | 611 | 616 | 397 |
| 8 | 635 | 624 | 628 | 404 |
| 9 | 647 | 626 | 633 | 407 |
| 10 | 692 | 638 | 658 | 423 |
| 11 | 693 | 663 | 677 | 434 |
| 12 | 689 | 650 | 669 | 429 |
| 13 | 768 | 663 | 703 | 450 |
| 14 | 698 | 666 | 688 | 441 |
| 15 | 681 | 633 | 662 | 425 |
| 16 | 703 | 678 | 687 | 441 |
| 17 | 717 | 690 | 704 | 451 |
| 18 | 716 | 709 | 712 | 456 |
| 19 | 721 | 712 | 717 | 459 |
| 20 | 724 | 712 | 719 | 460 |
| 21 | 748 | 720 | 738 | 472 |
| 22 | 733 | 698 | 708 | 454 |
| 23 | 701 | 693 | 697 | 447 |
| 24 | 710 | 696 | 703 | 450 |
| 25 | 710 | 698 | 705 | 452 |
| 26 | 703 | 696 | 700 | 449 |
| 27 | 705 | 680 | 693 | 444 |
| 28 | 692 | 678 | 684 | 439 |
| 29 | 684 | 676 | 681 | 437 |
| 30 | 681 | 674 | 678 | 435 |
| TOTAL | | | 20,306 | |

Comments:

0 reading indicates that the station was out of service.