

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 21
WATER QUALITY REPORT

RUN DATE: October 19, 2011

SEPTEMBER 2011

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|------|-----|--------------|-----|
| 1 | 289 | 261 | 276 | 187 |
| 2 | 289 | 266 | 280 | 189 |
| 3 | 292 | 249 | 275 | 186 |
| 4 | 263 | 236 | 251 | 171 |
| 5 | 278 | 252 | 263 | 179 |
| 6 | 269 | 252 | 261 | 177 |
| 7 | 256 | 244 | 251 | 171 |
| 8 | 272 | 238 | 259 | 176 |
| 9 | 305 | 239 | 274 | 185 |
| 10 | 327 | 244 | 286 | 193 |
| 11 | 330 | 250 | 290 | 195 |
| 12 | 330 | 254 | 293 | 197 |
| 13 | 323 | 255 | 289 | 195 |
| 14 | 333 | 243 | 285 | 192 |
| 15 | 386 | 243 | 306 | 205 |
| 16 | 412 | 236 | 302 | 203 |
| 17 | 416 | 267 | 331 | 221 |
| 18 | 429 | 241 | 328 | 219 |
| 19 | 431 | 248 | 337 | 224 |
| 20 | 407 | 241 | 317 | 212 |
| 21 | 403 | 239 | 317 | 212 |
| 22 | 368 | 252 | 309 | 207 |
| 23 | 372 | 254 | 315 | 211 |
| 24 | 385 | 248 | 320 | 214 |
| 25 | 381 | 248 | 314 | 210 |
| 26 | 369 | 258 | 311 | 208 |
| 27 | 356 | 252 | 302 | 203 |
| 28 | 364 | 266 | 316 | 211 |
| 29 | 364 | 275 | 322 | 215 |
| 30 | 365 | 266 | 317 | 212 |
| TOTAL | | | 8,897 | |

Comments:

0 reading indicates that the station was out of service.