

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

JULY 2014

**DELTA MENDOTA CANAL AT HEADWORKS
WATER QUALITY REPORT**

RUN DATE: August 8, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 732 | 689 | 704 | 451 |
| 2 | 705 | 677 | 692 | 444 |
| 3 | 701 | 667 | 684 | 439 |
| 4 | 700 | 682 | 689 | 442 |
| 5 | 697 | 669 | 688 | 441 |
| 6 | 695 | 672 | 681 | 437 |
| 7 | 687 | 660 | 674 | 433 |
| 8 | 686 | 658 | 672 | 431 |
| 9 | 685 | 655 | 671 | 431 |
| 10 | 673 | 655 | 662 | 425 |
| 11 | 698 | 658 | 671 | 431 |
| 12 | 678 | 651 | 661 | 424 |
| 13 | 678 | 654 | 664 | 426 |
| 14 | 682 | 646 | 668 | 429 |
| 15 | 676 | 631 | 650 | 418 |
| 16 | 646 | 633 | 639 | 411 |
| 17 | 658 | 632 | 645 | 415 |
| 18 | 656 | 637 | 644 | 414 |
| 19 | 648 | 625 | 636 | 409 |
| 20 | 660 | 623 | 639 | 411 |
| 21 | 637 | 618 | 628 | 404 |
| 22 | 637 | 624 | 630 | 405 |
| 23 | 646 | 628 | 635 | 408 |
| 24 | 647 | 616 | 630 | 405 |
| 25 | 648 | 619 | 639 | 411 |
| 26 | 647 | 623 | 637 | 410 |
| 27 | 640 | 624 | 632 | 407 |
| 28 | 644 | 624 | 634 | 408 |
| 29 | 656 | 630 | 644 | 414 |
| 30 | 645 | 630 | 638 | 410 |
| 31 | 652 | 634 | 644 | 414 |
| TOTAL | | | 20,325 | |

Comments:

0 reading indicates that the station was out of service.