

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT HEADWORKS
WATER QUALITY REPORT

JULY 2015

RUN DATE: August 21, 2015

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|-------------|------------|---------------|------------|
| 1 | 811 | 798 | 802 | 512 |
| 2 | 813 | 778 | 802 | 512 |
| 3 | 812 | 801 | 805 | 513 |
| 4 | 810 | 803 | 806 | 514 |
| 5 | 809 | 798 | 802 | 512 |
| 6 | 806 | 766 | 783 | 500 |
| 7 | 774 | 763 | 766 | 489 |
| 8 | 775 | 765 | 768 | 491 |
| 9 | 781 | 764 | 768 | 491 |
| 10 | 775 | 761 | 764 | 488 |
| 11 | 771 | 763 | 767 | 490 |
| 12 | 774 | 766 | 769 | 491 |
| 13 | 776 | 764 | 768 | 491 |
| 14 | 773 | 764 | 766 | 489 |
| 15 | 771 | 758 | 765 | 489 |
| 16 | 770 | 762 | 764 | 488 |
| 17 | 772 | 765 | 768 | 491 |
| 18 | 774 | 765 | 767 | 490 |
| 19 | 770 | 761 | 764 | 488 |
| 20 | 768 | 758 | 762 | 487 |
| 21 | 770 | 759 | 762 | 487 |
| 22 | 770 | 757 | 761 | 486 |
| 23 | 767 | 741 | 756 | 483 |
| 24 | 764 | 756 | 759 | 485 |
| 25 | 766 | 755 | 759 | 485 |
| 26 | 768 | 756 | 763 | 488 |
| 27 | 769 | 758 | 762 | 487 |
| 28 | 769 | 753 | 761 | 486 |
| 29 | 772 | 759 | 762 | 487 |
| 30 | 770 | 661 | 757 | 484 |
| 31 | 765 | 758 | 760 | 486 |
| TOTAL | | | 23,888 | |

Comments:

0 reading indicates that the station was out of service.