# UNITED STATES DEPARTMENT OF THE INTERIOR U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

## **DELTA MENDOTA CANAL AT HEADWORKS**

**JULY 2020** 

### WATER QUALITY REPORT

RUN DATE: August 4, 2020

## ELECTRICAL CONDUCTIVITY, UMHOS

| DAY    | HIGH | LOW | MEAN | TDS |
|--------|------|-----|------|-----|
| 1      | 0    | 0   | 0    | 0   |
| 2      | 0    | 0   | 0    | 0   |
| 2<br>3 | 0    | 0   | 0    | 0   |
| 4      | 0    | 0   | 0    | 0   |
| 5      | 0    | 0   | 0    | 0   |
| 6      | 0    | 0   | 0    | 0   |
| 7      | 0    | 0   | 0    | 0   |
| 8<br>9 | 0    | 0   | 0    | 0   |
| 9      | 0    | 0   | 0    | 0   |
| 10     | 0    | 0   | 0    | 0   |
| 11     | 0    | 0   | 0    | 0   |
| 12     | 0    | 0   | 0    | 0   |
| 13     | 0    | 0   | 0    | 0   |
| 14     | 0    | 0   | 0    | 0   |
| 15     | 0    | 0   | 0    | 0   |
| 16     | 0    | 0   | 0    | 0   |
| 17     | 0    | 0   | 0    | 0   |
| 18     | 0    | 0   | 0    | 0   |
| 19     | 0    | 0   | 0    | 0   |
| 20     | 0    | 0   | 0    | 0   |
| 21     | 0    | 0   | 0    | 0   |
| 22     | 0    | 0   | 0    | 0   |
| 23     | 0    | 0   | 0    | 0   |
| 24     | 0    | 0   | 0    | 0   |
| 25     | 0    | 0   | 0    | 0   |
| 26     | 0    | 0   | 0    | 0   |
| 27     | 0    | 0   | 0    | 0   |
| 28     | 0    | 0   | 0    | 0   |
| 29     | 311  | 280 | 294  | 198 |
| 30     | 301  | 281 | 290  | 195 |
| 31     | 303  | 287 | 294  | 198 |
| TOTAL  |      |     | 878  |     |

#### Comments:

0 reading indicates that the station was out of service.