

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT HEADWORKS
WATER QUALITY REPORT

SEPTEMBER 2005

RUN DATE: October 4, 2005

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|------|-----|---------------|-----|
| 1 | 323 | 277 | 301 | 202 |
| 2 | 326 | 284 | 310 | 208 |
| 3 | 354 | 312 | 327 | 218 |
| 4 | 353 | 315 | 336 | 224 |
| 5 | 369 | 305 | 338 | 225 |
| 6 | 359 | 318 | 344 | 229 |
| 7 | 357 | 343 | 351 | 233 |
| 8 | 354 | 348 | 351 | 233 |
| 9 | 346 | 333 | 340 | 226 |
| 10 | 363 | 327 | 347 | 230 |
| 11 | 362 | 332 | 345 | 229 |
| 12 | 384 | 333 | 352 | 234 |
| 13 | 368 | 326 | 347 | 230 |
| 14 | 383 | 335 | 360 | 238 |
| 15 | 366 | 341 | 357 | 237 |
| 16 | 357 | 342 | 350 | 232 |
| 17 | 356 | 342 | 349 | 232 |
| 18 | 353 | 345 | 349 | 232 |
| 19 | 345 | 333 | 339 | 226 |
| 20 | 343 | 331 | 338 | 225 |
| 21 | 341 | 332 | 337 | 224 |
| 22 | 341 | 334 | 338 | 225 |
| 23 | 346 | 338 | 342 | 227 |
| 24 | 345 | 339 | 342 | 227 |
| 25 | 340 | 328 | 333 | 222 |
| 26 | 334 | 321 | 327 | 218 |
| 27 | 337 | 330 | 332 | 221 |
| 28 | 334 | 321 | 328 | 219 |
| 29 | 321 | 282 | 296 | 199 |
| 30 | 283 | 272 | 279 | 188 |
| TOTAL | | | 10,085 | |

Comments:

0 reading indicates that the station was out of service.