

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

EMMATON BOTTOM ON THE SACRAMENTO RIVER

DECEMBER 2021

WATER QUALITY REPORT

RUN DATE: January 27, 2022

ELECTRICAL CONDUCTIVITY, UMHOS

DAY	HIGH	LOW	MEAN	14 DAY ACCUM MEAN	14 DAY AVG MEAN
1	7,942	1,748	4,321	44,636	3,188
2	8,673	1,446	4,833	47,338	3,381
3	10,339	1,885	5,727	50,622	3,616
4	10,699	2,372	6,063	54,097	3,864
5	9,718	1,426	5,564	56,782	4,056
6	9,416	1,053	5,460	59,071	4,219
7	9,730	1,130	5,574	61,174	4,370
8	8,920	1,212	5,559	63,647	4,546
9	7,882	1,617	5,352	66,264	4,733
10	6,947	1,360	4,356	67,593	4,828
11	6,769	835	3,951	68,116	4,865
12	7,560	1,275	4,636	69,190	4,942
13	8,906	1,882	5,490	70,975	5,070
14	7,251	565	3,516	70,402	5,029
15	4,399	528	1,997	68,078	4,863
16	3,169	536	1,047	64,292	4,592
17	1,610	327	606	59,171	4,227
18	1,111	328	490	53,598	3,828
19	1,403	306	536	48,570	3,469
20	1,118	320	481	43,591	3,114
21	1,132	374	535	38,552	2,754
22	1,017	419	550	33,543	2,396
23	1,118	420	581	28,772	2,055
24	574	352	423	24,839	1,774
25	488	296	391	21,279	1,520
26	398	295	330	16,973	1,212
27	357	257	295	11,778	841
28	308	216	252	8,514	608
29	308	211	247	6,764	483
30	317	211	239	5,956	425
31	298	204	234	5,584	399

Comments:

0 reading indicates that the station was out of service.