

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**FARRAR PARK AT DUTCH SLOUGH**  
**WATER QUALITY REPORT**

**FEBRUARY 2011**

RUN DATE: March 30, 2011

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 253  | 244 | 249  |
| 2   | 261  | 242 | 251  |
| 3   | 258  | 243 | 251  |
| 4   | 258  | 248 | 252  |
| 5   | 255  | 233 | 249  |
| 6   | 255  | 228 | 246  |
| 7   | 256  | 243 | 251  |
| 8   | 254  | 231 | 246  |
| 9   | 279  | 239 | 254  |
| 10  | 263  | 234 | 252  |
| 11  | 266  | 232 | 254  |
| 12  | 266  | 240 | 255  |
| 13  | 282  | 244 | 258  |
| 14  | 269  | 246 | 258  |
| 15  | 276  | 255 | 259  |
| 16  | 268  | 236 | 254  |
| 17  | 272  | 251 | 260  |
| 18  | 269  | 259 | 263  |
| 19  | 289  | 262 | 273  |
| 20  | 297  | 266 | 279  |
| 21  | 299  | 261 | 283  |
| 22  | 295  | 265 | 283  |
| 23  | 309  | 278 | 288  |
| 24  | 308  | 279 | 289  |
| 25  | 310  | 276 | 287  |
| 26  | 312  | 285 | 296  |
| 27  | 308  | 286 | 295  |
| 28  | 314  | 284 | 294  |

Comments:

0 reading indicates that the station was out of service.