

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**MARCH 2001**  
**FARRAR PARK AT DUTCH SLOUGH**  
**WATER QUALITY REPORT**

RUN DATE: April 9, 2001

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 442  | 382 | 408  |
| 2   | 430  | 369 | 401  |
| 3   | 433  | 362 | 399  |
| 4   | 429  | 351 | 395  |
| 5   | 416  | 340 | 389  |
| 6   | 417  | 347 | 386  |
| 7   | 409  | 331 | 379  |
| 8   | 378  | 325 | 351  |
| 9   | 363  | 314 | 340  |
| 10  | 350  | 307 | 329  |
| 11  | 348  | 301 | 321  |
| 12  | 331  | 296 | 313  |
| 13  | 353  | 299 | 316  |
| 14  | 349  | 299 | 314  |
| 15  | 342  | 301 | 313  |
| 16  | 323  | 252 | 300  |
| 17  | 351  | 277 | 298  |
| 18  | 347  | 278 | 297  |
| 19  | 299  | 280 | 293  |
| 20  | 341  | 279 | 296  |
| 21  | 319  | 272 | 287  |
| 22  | 292  | 254 | 272  |
| 23  | 292  | 259 | 272  |
| 24  | 276  | 262 | 270  |
| 25  | 274  | 267 | 270  |
| 26  | 322  | 266 | 276  |
| 27  | 287  | 263 | 272  |
| 28  | 280  | 263 | 272  |
| 29  | 274  | 256 | 268  |
| 30  | 290  | 261 | 270  |
| 31  | 321  | 263 | 276  |

Comments:

0 reading indicates that the station was out of service.