

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**MAY 2004** **FARRAR PARK AT DUTCH SLOUGH**  
**WATER QUALITY REPORT**

RUN DATE: June 8, 2004

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 202  | 180 | 190  |
| 2   | 199  | 187 | 191  |
| 3   | 196  | 187 | 190  |
| 4   | 197  | 178 | 190  |
| 5   | 199  | 192 | 194  |
| 6   | 204  | 186 | 199  |
| 7   | 207  | 194 | 202  |
| 8   | 208  | 189 | 203  |
| 9   | 214  | 204 | 208  |
| 10  | 216  | 190 | 205  |
| 11  | 228  | 199 | 212  |
| 12  | 225  | 173 | 200  |
| 13  | 219  | 194 | 206  |
| 14  | 220  | 188 | 205  |
| 15  | 218  | 190 | 207  |
| 16  | 222  | 189 | 208  |
| 17  | 218  | 186 | 201  |
| 18  | 228  | 188 | 206  |
| 19  | 227  | 195 | 212  |
| 20  | 236  | 186 | 224  |
| 21  | 235  | 203 | 223  |
| 22  | 237  | 197 | 219  |
| 23  | 234  | 184 | 208  |
| 24  | 236  | 190 | 216  |
| 25  | 238  | 190 | 219  |
| 26  | 247  | 208 | 231  |
| 27  | 249  | 205 | 237  |
| 28  | 247  | 220 | 239  |
| 29  | 262  | 206 | 237  |
| 30  | 252  | 230 | 245  |
| 31  | 262  | 237 | 248  |

Comments:

0 reading indicates that the station was out of service.