

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

JUNE 2020

FARRAR PARK AT DUTCH SLOUGH
WATER QUALITY REPORT

RUN DATE: July 9, 2020

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 267 | 261 | 264 |
| 2 | 266 | 257 | 263 |
| 3 | 266 | 257 | 263 |
| 4 | 267 | 261 | 264 |
| 5 | 288 | 261 | 269 |
| 6 | 307 | 262 | 279 |
| 7 | 304 | 263 | 285 |
| 8 | 294 | 260 | 278 |
| 9 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 |
| 30 | 310 | 280 | 292 |

Comments:

0 reading indicates that the station was out of service.