

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

JULY 2005

**FARRAR PARK AT DUTCH SLOUGH
WATER QUALITY REPORT**

RUN DATE: August 2, 2005

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 174 | 153 | 166 |
| 2 | 178 | 155 | 168 |
| 3 | 176 | 154 | 169 |
| 4 | 176 | 152 | 167 |
| 5 | 173 | 155 | 165 |
| 6 | 173 | 150 | 163 |
| 7 | 169 | 151 | 162 |
| 8 | 168 | 154 | 163 |
| 9 | 170 | 153 | 163 |
| 10 | 171 | 153 | 164 |
| 11 | 173 | 156 | 165 |
| 12 | 173 | 158 | 166 |
| 13 | 179 | 163 | 170 |
| 14 | 186 | 164 | 173 |
| 15 | 187 | 167 | 177 |
| 16 | 194 | 167 | 182 |
| 17 | 192 | 170 | 185 |
| 18 | 195 | 170 | 185 |
| 19 | 199 | 171 | 188 |
| 20 | 209 | 175 | 193 |
| 21 | 219 | 178 | 199 |
| 22 | 227 | 179 | 205 |
| 23 | 232 | 185 | 205 |
| 24 | 230 | 176 | 209 |
| 25 | 241 | 180 | 214 |
| 26 | 256 | 199 | 222 |
| 27 | 272 | 210 | 231 |
| 28 | 285 | 210 | 243 |
| 29 | 313 | 219 | 259 |
| 30 | 313 | 233 | 275 |
| 31 | 329 | 237 | 283 |

Comments:

0 reading indicates that the station was out of service.