

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**FARRAR PARK AT DUTCH SLOUGH**  
**WATER QUALITY REPORT**

**SEPTEMBER 2004**

RUN DATE: October 13, 2004

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH  | LOW   | MEAN  |
|-----|-------|-------|-------|
| 1   | 797   | 602   | 697   |
| 2   | 799   | 626   | 707   |
| 3   | 824   | 624   | 705   |
| 4   | 790   | 614   | 681   |
| 5   | 819   | 623   | 706   |
| 6   | 843   | 636   | 733   |
| 7   | 874   | 615   | 747   |
| 8   | 875   | 644   | 759   |
| 9   | 882   | 643   | 771   |
| 10  | 931   | 665   | 790   |
| 11  | 945   | 680   | 801   |
| 12  | 958   | 689   | 830   |
| 13  | 1,005 | 713   | 847   |
| 14  | 980   | 704   | 824   |
| 15  | 946   | 698   | 830   |
| 16  | 977   | 698   | 848   |
| 17  | 1,078 | 775   | 888   |
| 18  | 1,131 | 797   | 933   |
| 19  | 1,130 | 776   | 944   |
| 20  | 1,078 | 798   | 920   |
| 21  | 1,057 | 767   | 903   |
| 22  | 1,006 | 771   | 909   |
| 23  | 999   | 783   | 912   |
| 24  | 1,024 | 796   | 919   |
| 25  | 1,051 | 815   | 940   |
| 26  | 1,092 | 789   | 954   |
| 27  | 1,098 | 827   | 972   |
| 28  | 1,369 | 829   | 1,062 |
| 29  | 1,381 | 1,061 | 1,205 |
| 30  | 1,439 | 1,064 | 1,220 |

Comments:

0 reading indicates that the station was out of service.