UNITED STATES DEPARTMENT OF THE INTERIOR U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

SEPTEMBER 2009

FARRAR PARK AT DUTCH SLOUGH WATER QUALITY REPORT

Y REPORT RUN DATE: October 2, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

DAY	HIGH	LOW	MEAN	
1 2 3	1,322 1,296	1,022 1,011	1,152 1,143	
3	1,274	1,042	1,158	
4	1,281	1,063	1,176	
5	1,296	1,071	1,180	
6	1,313	1,059	1,183	
7	1,302	1,077	1,179	
8	1,318	1,091	1,189	
9	1,363	1,106	1,215	
10	1,386	1,099	1,216	
11	1,392	1,094	1,229	
12	1,507	1,123	1,272	
13	1,518	1,101	1,261	
14	1,481	1,097	1,232	
15	1,419	1,098	1,223	
16	1,349	1,102	1,214	
17	1,328	1,098	1,208	
18	1,304	1,099	1,200	
19	1,304	1,118	1,205	
20	1,314	1,120	1,201	
21	1,325	1,114	1,199	
22	1,319	1,103	1,193	
23	1,312	1,048	1,186	
24	1,313	1,074	1,190	
25	1,308	1,079	1,175	
26	1,285	1,028	1,149	
27	1,233	1,022	1,118	
28	1,214	996	1,122	
29	1,246	1,033	1,135	
30	1,262	991	1,104	

Comments:

0 reading indicates that the station was out of service.