

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

FARRAR PARK AT DUTCH SLOUGH
WATER QUALITY REPORT

SEPTEMBER 2017

RUN DATE: October 3, 2017

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 205 | 174 | 193 |
| 2 | 189 | 159 | 173 |
| 3 | 188 | 154 | 175 |
| 4 | 170 | 152 | 162 |
| 5 | 182 | 150 | 169 |
| 6 | 172 | 145 | 158 |
| 7 | 175 | 148 | 161 |
| 8 | 176 | 146 | 164 |
| 9 | 173 | 147 | 163 |
| 10 | 173 | 150 | 166 |
| 11 | 172 | 148 | 163 |
| 12 | 162 | 141 | 155 |
| 13 | 176 | 147 | 158 |
| 14 | 173 | 141 | 155 |
| 15 | 159 | 132 | 148 |
| 16 | 147 | 126 | 135 |
| 17 | 147 | 127 | 139 |
| 18 | 204 | 125 | 167 |
| 19 | 201 | 193 | 198 |
| 20 | 201 | 195 | 198 |
| 21 | 202 | 195 | 198 |
| 22 | 199 | 194 | 197 |
| 23 | 200 | 193 | 196 |
| 24 | 198 | 191 | 194 |
| 25 | 196 | 186 | 192 |
| 26 | 193 | 182 | 190 |
| 27 | 192 | 180 | 189 |
| 28 | 192 | 181 | 189 |
| 29 | 195 | 181 | 190 |
| 30 | 194 | 186 | 190 |

Comments:

0 reading indicates that the station was out of service.