UNITED STATES DEPARTMENT OF THE INTERIOR U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

SEPTEMBER 2020

FARRAR PARK AT DUTCH SLOUGH

WATER QUALITY REPORT RUN DATE: October 19, 2020

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | |
|-----|-------|-------|-------|--|
| 1 | 1,977 | 1,392 | 1,731 | |
| 2 | 1,991 | 1,369 | 1,696 | |
| 3 | 1,933 | 1,381 | 1,664 | |
| 4 | 1,853 | 1,384 | 1,623 | |
| 5 | 1,741 | 1,371 | 1,560 | |
| 6 | 1,639 | 1,367 | 1,508 | |
| 7 | 1,565 | 1,370 | 1,474 | |
| 8 | 1,542 | 1,365 | 1,457 | |
| 9 | 1,541 | 1,334 | 1,439 | |
| 10 | 1,531 | 1,301 | 1,415 | |
| 11 | 1,474 | 1,234 | 1,376 | |
| 12 | 1,390 | 1,195 | 1,319 | |
| 13 | 1,311 | 1,160 | 1,266 | |
| 14 | 1,286 | 1,165 | 1,238 | |
| 15 | 1,269 | 1,145 | 1,224 | |
| 16 | 1,248 | 1,138 | 1,202 | |
| 17 | 1,213 | 1,119 | 1,180 | |
| 18 | 1,194 | 1,129 | 1,171 | |
| 19 | 1,202 | 1,115 | 1,162 | |
| 20 | 1,191 | 1,104 | 1,152 | |
| 21 | 1,258 | 1,095 | 1,155 | |
| 22 | 1,265 | 1,066 | 1,151 | |
| 23 | 1,223 | 1,026 | 1,143 | |
| 24 | 1,239 | 1,026 | 1,153 | |
| 25 | 1,237 | 1,022 | 1,146 | |
| 26 | 1,235 | 1,005 | 1,135 | |
| 27 | 1,199 | 996 | 1,123 | |
| 28 | 1,187 | 1,018 | 1,118 | |
| 29 | 1,214 | 1,036 | 1,128 | |
| 30 | 1,241 | 1,053 | 1,152 | |

Comments:

0 reading indicates that the station was out of service.