

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

FARRAR PARK AT DUTCH SLOUGH
WATER QUALITY REPORT

OCTOBER 2006

RUN DATE: November 3, 2006

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 397 | 319 | 360 |
| 2 | 378 | 314 | 352 |
| 3 | 364 | 320 | 347 |
| 4 | 365 | 321 | 349 |
| 5 | 363 | 323 | 346 |
| 6 | 366 | 322 | 346 |
| 7 | 368 | 322 | 344 |
| 8 | 367 | 318 | 343 |
| 9 | 383 | 316 | 346 |
| 10 | 399 | 315 | 356 |
| 11 | 404 | 313 | 358 |
| 12 | 420 | 313 | 365 |
| 13 | 445 | 328 | 376 |
| 14 | 436 | 331 | 378 |
| 15 | 441 | 337 | 377 |
| 16 | 421 | 340 | 379 |
| 17 | 422 | 343 | 382 |
| 18 | 423 | 344 | 379 |
| 19 | 420 | 353 | 385 |
| 20 | 419 | 348 | 383 |
| 21 | 460 | 359 | 405 |
| 22 | 465 | 358 | 410 |
| 23 | 482 | 361 | 418 |
| 24 | 511 | 356 | 435 |
| 25 | 557 | 368 | 443 |
| 26 | 499 | 376 | 436 |
| 27 | 505 | 382 | 442 |
| 28 | 540 | 380 | 459 |
| 29 | 609 | 381 | 492 |
| 30 | 595 | 399 | 485 |
| 31 | 595 | 393 | 482 |

Comments:

0 reading indicates that the station was out of service.