

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**FARRAR PARK AT DUTCH SLOUGH**  
**WATER QUALITY REPORT**

**DECEMBER 2006**

RUN DATE: January 4, 2007

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH  | LOW | MEAN  |
|-----|-------|-----|-------|
| 1   | 980   | 755 | 878   |
| 2   | 1,059 | 812 | 919   |
| 3   | 1,076 | 820 | 931   |
| 4   | 1,135 | 802 | 953   |
| 5   | 1,152 | 813 | 964   |
| 6   | 1,120 | 809 | 967   |
| 7   | 1,111 | 806 | 966   |
| 8   | 1,151 | 796 | 991   |
| 9   | 1,207 | 866 | 1,031 |
| 10  | 1,118 | 866 | 1,000 |
| 11  | 1,082 | 822 | 955   |
| 12  | 1,047 | 839 | 951   |
| 13  | 1,053 | 805 | 950   |
| 14  | 1,056 | 877 | 953   |
| 15  | 1,117 | 893 | 980   |
| 16  | 1,124 | 905 | 1,006 |
| 17  | 1,184 | 865 | 1,025 |
| 18  | 1,112 | 883 | 1,012 |
| 19  | 1,145 | 843 | 1,017 |
| 20  | 1,139 | 822 | 1,015 |
| 21  | 1,157 | 859 | 1,031 |
| 22  | 1,183 | 883 | 1,035 |
| 23  | 1,109 | 880 | 1,016 |
| 24  | 1,077 | 878 | 1,006 |
| 25  | 1,055 | 893 | 1,000 |
| 26  | 1,044 | 924 | 1,006 |
| 27  | 1,102 | 987 | 1,038 |
| 28  | 1,074 | 899 | 970   |
| 29  | 1,046 | 906 | 974   |
| 30  | 1,015 | 923 | 979   |
| 31  | 991   | 908 | 965   |

Comments:

0 reading indicates that the station was out of service.