UNITED STATES DEPARTMENT OF THE INTERIOR U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DECEMBER 2008

FARRAR PARK AT DUTCH SLOUGH

WATER QUALITY REPORT RUN DATE: January 6, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

DAY	HIGH	LOW	MEAN
1	1,382	1,093	1,222
2	1,322	1,092	1,201
3	1,258	1,067	1,166
4	1,231	1,061	1,154
5	1,218	1,069	1,141
6	1,208	1,067	1,130
7	1,227	1,068	1,135
8	1,224	1,039	1,130
9	1,235	1,020	1,124
10	1,262	998	1,114
11	1,309	1,011	1,137
12	1,393	1,004	1,170
13	1,854	1,004	1,339
14	1,798	1,070	1,355
15	1,835	1,125	1,417
16	1,599	1,140	1,359
17	1,581	1,104	1,306
18	1,478	1,123	1,288
19	1,487	1,169	1,280
20	1,454	1,159	1,266
21	1,452	1,146	1,274
22	1,452	1,172	1,318
23	1,454	1,137	1,307
24	1,410	1,127	1,272
25	1,538	1,131	1,346
26 27 28 29 30 31	2,058 1,684 1,540 1,421 1,339 1,281	1,106 1,067 1,082 1,094 1,099	1,419 1,317 1,289 1,263 1,228 1,197

Comments:

0 reading indicates that the station was out of service.