

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**HOLLAND TRACT ON OLD RIVER**  
**WATER QUALITY REPORT**

**OCTOBER 2019**

RUN DATE: November 13, 2019

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 162  | 151 | 155  |
| 2   | 163  | 151 | 154  |
| 3   | 163  | 150 | 154  |
| 4   | 158  | 150 | 153  |
| 5   | 155  | 149 | 151  |
| 6   | 153  | 148 | 149  |
| 7   | 151  | 145 | 148  |
| 8   | 150  | 143 | 146  |
| 9   | 147  | 143 | 145  |
| 10  | 150  | 146 | 149  |
| 11  | 151  | 146 | 149  |
| 12  | 151  | 145 | 148  |
| 13  | 150  | 144 | 147  |
| 14  | 151  | 143 | 147  |
| 15  | 150  | 126 | 144  |
| 16  | 150  | 143 | 147  |
| 17  | 150  | 143 | 146  |
| 18  | 151  | 142 | 146  |
| 19  | 151  | 143 | 147  |
| 20  | 153  | 143 | 148  |
| 21  | 155  | 142 | 149  |
| 22  | 157  | 143 | 149  |
| 23  | 160  | 137 | 148  |
| 24  | 156  | 142 | 148  |
| 25  | 159  | 143 | 149  |
| 26  | 160  | 144 | 150  |
| 27  | 156  | 130 | 144  |
| 28  | 159  | 137 | 147  |
| 29  | 159  | 142 | 151  |
| 30  | 163  | 149 | 157  |
| 31  | 171  | 153 | 162  |

Comments:

0 reading indicates that the station was out of service.