

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)

JANUARY 2017

WATER QUALITY REPORT

RUN DATE: February 1, 2017

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 534 | 367 | 452 |
| 2 | 591 | 394 | 451 |
| 3 | 582 | 390 | 467 |
| 4 | 555 | 415 | 488 |
| 5 | 501 | 426 | 471 |
| 6 | 687 | 433 | 535 |
| 7 | 623 | 472 | 555 |
| 8 | 786 | 560 | 697 |
| 9 | 636 | 233 | 456 |
| 10 | 349 | 218 | 276 |
| 11 | 277 | 241 | 261 |
| 12 | 341 | 255 | 307 |
| 13 | 362 | 246 | 329 |
| 14 | 360 | 226 | 297 |
| 15 | 339 | 227 | 277 |
| 16 | 329 | 243 | 284 |
| 17 | 330 | 261 | 298 |
| 18 | 359 | 263 | 310 |
| 19 | 320 | 246 | 290 |
| 20 | 316 | 207 | 267 |
| 21 | 233 | 189 | 208 |
| 22 | 274 | 237 | 257 |
| 23 | 380 | 234 | 305 |
| 24 | 348 | 215 | 289 |
| 25 | 328 | 258 | 302 |
| 26 | 333 | 292 | 309 |
| 27 | 345 | 293 | 323 |
| 28 | 358 | 326 | 343 |
| 29 | 357 | 304 | 326 |
| 30 | 345 | 303 | 322 |
| 31 | 346 | 315 | 334 |

Comments:

0 reading indicates that the station was out of service.