

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)**

**JANUARY 2020**

**WATER QUALITY REPORT**

RUN DATE: February 12, 2020

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 558  | 329 | 413  |
| 2   | 568  | 341 | 420  |
| 3   | 560  | 338 | 411  |
| 4   | 574  | 344 | 428  |
| 5   | 562  | 350 | 420  |
| 6   | 562  | 354 | 434  |
| 7   | 597  | 353 | 434  |
| 8   | 581  | 349 | 421  |
| 9   | 581  | 350 | 411  |
| 10  | 558  | 344 | 406  |
| 11  | 571  | 349 | 404  |
| 12  | 561  | 351 | 416  |
| 13  | 562  | 352 | 403  |
| 14  | 559  | 350 | 407  |
| 15  | 558  | 346 | 399  |
| 16  | 555  | 349 | 407  |
| 17  | 548  | 345 | 408  |
| 18  | 528  | 345 | 399  |
| 19  | 525  | 336 | 408  |
| 20  | 534  | 337 | 414  |
| 21  | 536  | 349 | 409  |
| 22  | 492  | 341 | 386  |
| 23  | 494  | 339 | 378  |
| 24  | 511  | 341 | 392  |
| 25  | 521  | 343 | 399  |
| 26  | 518  | 341 | 403  |
| 27  | 521  | 341 | 399  |
| 28  | 657  | 335 | 424  |
| 29  | 674  | 383 | 471  |
| 30  | 676  | 385 | 466  |
| 31  | 684  | 383 | 472  |

Comments:

0 reading indicates that the station was out of service.