

UNITED STATES DEPARTMENT OF THE INTERIOR  
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)**

**MAY 2021**

**WATER QUALITY REPORT**

RUN DATE: June 1, 2021

**ELECTRICAL CONDUCTIVITY, UMHOS**

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1   | 543  | 482 | 511  |
| 2   | 533  | 433 | 487  |
| 3   | 522  | 430 | 467  |
| 4   | 530  | 442 | 486  |
| 5   | 621  | 511 | 572  |
| 6   | 598  | 554 | 587  |
| 7   | 595  | 549 | 575  |
| 8   | 585  | 547 | 568  |
| 9   | 579  | 545 | 559  |
| 10  | 581  | 542 | 563  |
| 11  | 604  | 557 | 587  |
| 12  | 617  | 579 | 605  |
| 13  | 617  | 577 | 595  |
| 14  | 579  | 566 | 571  |
| 15  | 568  | 550 | 557  |
| 16  | 584  | 558 | 574  |
| 17  | 585  | 573 | 578  |
| 18  | 572  | 559 | 563  |
| 19  | 608  | 575 | 591  |
| 20  | 607  | 562 | 584  |
| 21  | 582  | 557 | 569  |
| 22  | 595  | 560 | 575  |
| 23  | 599  | 561 | 585  |
| 24  | 603  | 569 | 582  |
| 25  | 583  | 541 | 567  |
| 26  | 584  | 553 | 570  |
| 27  | 591  | 550 | 572  |
| 28  | 550  | 522 | 541  |
| 29  | 539  | 526 | 534  |
| 30  | 544  | 492 | 533  |
| 31  | 552  | 531 | 542  |

Comments:

0 reading indicates that the station was out of service.