

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)
WATER QUALITY REPORT

JULY 2001

RUN DATE: August 7, 2001

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 423 | 331 | 351 |
| 2 | 383 | 329 | 345 |
| 3 | 450 | 319 | 345 |
| 4 | 434 | 325 | 346 |
| 5 | 434 | 322 | 341 |
| 6 | 447 | 322 | 346 |
| 7 | 480 | 320 | 344 |
| 8 | 509 | 315 | 344 |
| 9 | 534 | 310 | 343 |
| 10 | 512 | 303 | 332 |
| 11 | 479 | 300 | 330 |
| 12 | 548 | 299 | 344 |
| 13 | 505 | 305 | 341 |
| 14 | 499 | 315 | 358 |
| 15 | 438 | 321 | 345 |
| 16 | 453 | 325 | 346 |
| 17 | 414 | 324 | 350 |
| 18 | 415 | 325 | 351 |
| 19 | 391 | 327 | 345 |
| 20 | 474 | 312 | 341 |
| 21 | 501 | 311 | 335 |
| 22 | 472 | 302 | 348 |
| 23 | 496 | 303 | 345 |
| 24 | 474 | 307 | 343 |
| 25 | 392 | 304 | 339 |
| 26 | 396 | 309 | 343 |
| 27 | 458 | 325 | 359 |
| 28 | 444 | 335 | 366 |
| 29 | 463 | 327 | 375 |
| 30 | 436 | 348 | 385 |
| 31 | 502 | 330 | 402 |

Comments:

0 reading indicates that the station was out of service.