

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)

SEPTEMBER 2011

WATER QUALITY REPORT

RUN DATE: October 19, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 225 | 187 | 212 |
| 2 | 231 | 193 | 214 |
| 3 | 250 | 220 | 231 |
| 4 | 240 | 217 | 226 |
| 5 | 230 | 218 | 224 |
| 6 | 247 | 212 | 229 |
| 7 | 280 | 210 | 245 |
| 8 | 313 | 215 | 252 |
| 9 | 303 | 216 | 262 |
| 10 | 308 | 215 | 261 |
| 11 | 308 | 212 | 257 |
| 12 | 316 | 208 | 253 |
| 13 | 347 | 209 | 267 |
| 14 | 414 | 212 | 282 |
| 15 | 398 | 207 | 282 |
| 16 | 428 | 209 | 295 |
| 17 | 456 | 208 | 304 |
| 18 | 414 | 211 | 304 |
| 19 | 403 | 209 | 300 |
| 20 | 356 | 212 | 287 |
| 21 | 358 | 219 | 282 |
| 22 | 369 | 221 | 294 |
| 23 | 363 | 217 | 284 |
| 24 | 354 | 221 | 287 |
| 25 | 344 | 221 | 281 |
| 26 | 347 | 227 | 285 |
| 27 | 351 | 231 | 293 |
| 28 | 343 | 225 | 286 |
| 29 | 332 | 229 | 287 |
| 30 | 341 | 233 | 286 |

Comments:

0 reading indicates that the station was out of service.