

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)

SEPTEMBER 2014

WATER QUALITY REPORT

RUN DATE: October 1, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 645 | 632 | 637 |
| 2 | 641 | 631 | 635 |
| 3 | 633 | 613 | 624 |
| 4 | 652 | 620 | 636 |
| 5 | 648 | 628 | 637 |
| 6 | 631 | 573 | 613 |
| 7 | 639 | 625 | 634 |
| 8 | 628 | 618 | 622 |
| 9 | 625 | 609 | 617 |
| 10 | 644 | 602 | 618 |
| 11 | 626 | 607 | 618 |
| 12 | 666 | 606 | 615 |
| 13 | 683 | 612 | 635 |
| 14 | 690 | 601 | 615 |
| 15 | 662 | 571 | 609 |
| 16 | 674 | 560 | 595 |
| 17 | 677 | 382 | 571 |
| 18 | 571 | 381 | 522 |
| 19 | 716 | 281 | 538 |
| 20 | 652 | 548 | 588 |
| 21 | 723 | 592 | 620 |
| 22 | 673 | 600 | 616 |
| 23 | 703 | 606 | 633 |
| 24 | 665 | 592 | 610 |
| 25 | 667 | 565 | 616 |
| 26 | 687 | 593 | 617 |
| 27 | 661 | 562 | 605 |
| 28 | 625 | 386 | 589 |
| 29 | 674 | 403 | 575 |
| 30 | 692 | 575 | 622 |

Comments:

0 reading indicates that the station was out of service.