

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

PORT CHICAGO BOTTOM IN SUISUN BAY
WATER QUALITY REPORT

MARCH 2011

RUN DATE: April 25, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|--------|-----|-------|
| 1 | 3,773 | 276 | 649 |
| 2 | 6,168 | 287 | 1,412 |
| 3 | 1,327 | 271 | 530 |
| 4 | 476 | 281 | 347 |
| 5 | 606 | 273 | 341 |
| 6 | 1,008 | 274 | 406 |
| 7 | 3,452 | 255 | 628 |
| 8 | 993 | 255 | 329 |
| 9 | 660 | 249 | 281 |
| 10 | 3,068 | 221 | 500 |
| 11 | 7,753 | 220 | 1,352 |
| 12 | 10,860 | 243 | 2,208 |
| 13 | 13,087 | 265 | 4,061 |
| 14 | 13,302 | 261 | 4,679 |
| 15 | 11,229 | 277 | 3,827 |
| 16 | 6,462 | 255 | 1,932 |
| 17 | 1,283 | 249 | 450 |
| 18 | 366 | 226 | 278 |
| 19 | 304 | 223 | 250 |
| 20 | 286 | 208 | 239 |
| 21 | 240 | 181 | 210 |
| 22 | 246 | 182 | 205 |
| 23 | 251 | 174 | 203 |
| 24 | 225 | 163 | 188 |
| 25 | 209 | 167 | 187 |
| 26 | 208 | 156 | 178 |
| 27 | 235 | 161 | 185 |
| 28 | 237 | 170 | 184 |
| 29 | 206 | 170 | 182 |
| 30 | 200 | 168 | 180 |
| 31 | 227 | 180 | 193 |

Comments:

0 reading indicates that the station was out of service.