

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIO VISTA ON THE SACRAMENTO RIVER
WATER QUALITY REPORT

JUNE 2009

RUN DATE: July 29, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 168 | 157 | 164 |
| 2 | 166 | 158 | 162 |
| 3 | 165 | 153 | 159 |
| 4 | 163 | 147 | 155 |
| 5 | 159 | 141 | 148 |
| 6 | 156 | 142 | 145 |
| 7 | 154 | 141 | 144 |
| 8 | 152 | 141 | 144 |
| 9 | 155 | 138 | 144 |
| 10 | 169 | 141 | 153 |
| 11 | 173 | 152 | 164 |
| 12 | 175 | 164 | 169 |
| 13 | 173 | 164 | 170 |
| 14 | 173 | 168 | 170 |
| 15 | 172 | 167 | 170 |
| 16 | 171 | 162 | 168 |
| 17 | 172 | 164 | 167 |
| 18 | 174 | 163 | 167 |
| 19 | 173 | 164 | 167 |
| 20 | 183 | 166 | 169 |
| 21 | 205 | 166 | 173 |
| 22 | 194 | 165 | 172 |
| 23 | 210 | 166 | 173 |
| 24 | 211 | 162 | 174 |
| 25 | 218 | 158 | 174 |
| 26 | 199 | 154 | 166 |
| 27 | 170 | 148 | 157 |
| 28 | 163 | 146 | 152 |
| 29 | 160 | 146 | 152 |
| 30 | 167 | 138 | 148 |

Comments:

0 reading indicates that the station was out of service.