

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIO VISTA ON THE SACRAMENTO RIVER
WATER QUALITY REPORT

JULY 2008

RUN DATE: August 1, 2008

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 152 | 72 | 94 |
| 2 | 167 | 80 | 98 |
| 3 | 170 | 73 | 100 |
| 4 | 163 | 72 | 99 |
| 5 | 147 | 79 | 99 |
| 6 | 113 | 79 | 95 |
| 7 | 109 | 88 | 96 |
| 8 | 109 | 78 | 94 |
| 9 | 117 | 76 | 94 |
| 10 | 130 | 78 | 92 |
| 11 | 142 | 80 | 97 |
| 12 | 149 | 79 | 96 |
| 13 | 169 | 77 | 100 |
| 14 | 211 | 79 | 111 |
| 15 | 199 | 74 | 108 |
| 16 | 231 | 77 | 109 |
| 17 | 235 | 81 | 109 |
| 18 | 200 | 75 | 108 |
| 19 | 207 | 87 | 115 |
| 20 | 194 | 83 | 113 |
| 21 | 140 | 84 | 103 |
| 22 | 135 | 87 | 98 |
| 23 | 121 | 72 | 95 |
| 24 | 143 | 83 | 100 |
| 25 | 173 | 80 | 103 |
| 26 | 191 | 80 | 108 |
| 27 | 210 | 80 | 110 |
| 28 | 255 | 82 | 120 |
| 29 | 395 | 84 | 148 |
| 30 | 462 | 88 | 155 |
| 31 | 391 | 81 | 147 |

Comments:

0 reading indicates that the station was out of service.