

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIO VISTA ON THE SACRAMENTO RIVER
WATER QUALITY REPORT

OCTOBER 2011

RUN DATE: November 9, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 151 | 138 | 141 |
| 2 | 154 | 137 | 143 |
| 3 | 147 | 129 | 137 |
| 4 | 142 | 125 | 132 |
| 5 | 135 | 120 | 128 |
| 6 | 139 | 118 | 128 |
| 7 | 137 | 118 | 129 |
| 8 | 135 | 120 | 128 |
| 9 | 134 | 120 | 127 |
| 10 | 133 | 121 | 126 |
| 11 | 133 | 122 | 126 |
| 12 | 136 | 125 | 129 |
| 13 | 138 | 124 | 130 |
| 14 | 139 | 126 | 130 |
| 15 | 138 | 124 | 129 |
| 16 | 136 | 127 | 130 |
| 17 | 142 | 127 | 132 |
| 18 | 145 | 128 | 133 |
| 19 | 141 | 130 | 132 |
| 20 | 143 | 127 | 132 |
| 21 | 144 | 128 | 134 |
| 22 | 145 | 130 | 137 |
| 23 | 142 | 133 | 137 |
| 24 | 139 | 133 | 136 |
| 25 | 137 | 132 | 135 |
| 26 | 138 | 130 | 133 |
| 27 | 144 | 132 | 135 |
| 28 | 146 | 133 | 137 |
| 29 | 144 | 136 | 138 |
| 30 | 144 | 136 | 138 |
| 31 | 144 | 136 | 139 |

Comments:

0 reading indicates that the station was out of service.