

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

WATER QUALITY REPORT

MAY 2009

RUN DATE: June 2, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	83	63	65	57.6	56.5	57.1	9.5	9.0	9.3
2	71	63	66	56.8	56.0	56.2	9.2	9.1	9.1
3	66	63	64	62.0	56.2	58.3	9.3	8.4	9.0
4	68	64	65	58.6	56.0	57.2	9.4	9.2	9.3
5	68	63	64	60.7	57.6	59.0	9.3	9.0	9.2
6	68	64	65	61.9	58.6	60.2	9.1	8.9	9.0
7	70	64	66	63.2	59.4	61.2	9.1	8.7	8.9
8	73	66	68	63.5	59.9	61.8	8.8	8.6	8.7
9	77	69	70	63.6	60.0	61.9	8.8	8.6	8.7
10	91	66	70	63.7	59.9	62.0	8.9	8.5	8.7
11	77	66	68	63.9	60.3	62.2	8.9	8.6	8.8
12	79	67	71	63.1	60.1	61.8	9.0	8.7	8.8
13	73	66	69	62.7	59.5	61.2	9.0	8.8	8.9
14	71	66	67	63.3	59.6	61.5	9.0	8.6	8.9
15	72	66	67	64.3	60.8	62.5	8.9	8.6	8.8
16	79	66	67	65.3	61.4	63.3	8.8	8.6	8.7
17	69	66	67	66.0	62.1	64.2	8.7	8.3	8.6
18	86	67	71	66.9	63.3	65.2	8.6	8.2	8.4
19	75	69	71	67.5	63.8	65.7	8.5	8.2	8.3
20	81	69	71	66.0	62.5	64.5	8.7	8.2	8.4
21	81	69	72	65.8	62.0	64.1	8.8	8.4	8.6
22	72	69	70	66.4	62.3	64.4	8.7	8.3	8.5
23	80	69	71	66.2	62.7	64.5	8.7	8.0	8.5
24	81	67	69	65.4	61.9	63.8	8.8	8.3	8.6
25	73	67	68	65.7	61.5	63.7	8.8	8.5	8.6
26	71	67	68	66.9	62.6	64.7	8.7	8.4	8.6
27	69	66	67	68.1	63.8	65.9	8.6	7.9	8.4
28	80	66	67	68.6	64.6	66.7	8.5	8.2	8.3
29	71	65	67	68.4	65.0	66.9	8.5	7.3	8.3
30	78	66	68	67.4	63.8	65.8	8.7	8.3	8.5
31	68	66	67	67.3	63.3	65.3	8.7	8.4	8.5

Comments:

0 reading indicates that the station was out of service.