

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

WATER QUALITY REPORT

MAY 2011

RUN DATE: July 12, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	80	70	75	56.2	54.3	55.2	10.0	9.9	10.0
2	77	69	72	56.9	54.5	55.6	10.1	9.9	10.0
3	71	67	68	57.2	55.4	56.2	10.1	9.9	9.9
4	76	66	69	57.5	55.4	56.3	10.0	9.9	9.9
5	72	66	68	58.2	55.7	56.8	10.0	9.8	9.9
6	66	65	66	58.4	56.4	57.3	9.9	9.7	9.8
7	74	66	70	57.6	55.9	56.6	9.9	9.8	9.8
8	67	65	66	56.9	55.0	55.9	10.0	9.8	9.9
9	71	64	67	55.3	53.8	54.6	10.1	9.9	10.0
10	66	64	65	56.7	54.1	55.3	10.1	9.9	10.0
11	74	66	68	57.8	56.0	56.7	9.9	9.8	9.9
12	70	64	66	57.7	55.6	56.6	10.0	9.8	9.9
13	68	64	65	57.7	55.6	56.5	10.0	9.8	9.9
14	69	64	66	56.4	55.2	55.9	9.9	9.8	9.8
15	72	63	67	55.5	54.2	54.9	10.0	9.7	9.8
16	70	64	65	55.0	53.7	54.3	10.0	9.7	9.9
17	67	64	65	54.0	53.4	53.7	10.1	9.9	10.0
18	71	63	65	54.4	52.9	53.6	10.1	9.9	10.0
19	67	63	64	56.3	54.0	55.0	10.1	9.9	10.0
20	65	64	65	57.8	55.4	56.5	10.0	9.7	9.8
21	70	64	66	58.2	56.4	57.2	9.8	9.6	9.7
22	70	64	66	57.7	55.9	56.7	9.8	9.6	9.7
23	70	64	66	57.1	55.4	56.2	9.8	9.7	9.8
24	72	64	66	57.4	55.3	56.3	9.9	9.7	9.8
25	71	64	66	56.4	55.0	55.8	9.9	9.7	9.8
26	68	64	66	55.9	53.3	54.6	9.9	9.8	9.9
27	70	64	66	57.4	55.3	56.3	10.0	9.7	9.8
28	72	64	70	57.7	55.4	56.4	9.8	9.2	9.5
29	77	68	70	57.7	55.0	56.3	9.6	9.4	9.5
30	74	66	68	58.1	56.0	57.0	9.6	9.5	9.5
31	75	66	68	58.2	56.4	57.3	9.7	9.4	9.5

Comments:

0 reading indicates that the station was out of service.